

PCN Number:	20180717001	PCN Date:	July 17, 2018
Title:	Datasheet for OPA354A-Q1, OPA2354A-Q1, OPA4354-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



OPA354A-Q1, OPA2354A-Q1, OPA4354-Q1
SBOS492F – JUNE 2009 – REVISED MAY 2018

Changes from Revision E (August 2016) to Revision F	Page
• Deleted table note about input terminals and input signals from <i>Absolute Maximum Ratings</i> table	6

The datasheet number will be changing.

Device Family	Change From:	Change To:
OPA354A-Q1, OPA2354A-Q1, OPA4354-Q1	SBOS492E	SBOS492F

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/OPA354A-Q1>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

OPA2354AQDGKRQ1	OPA354AQDBVRQ1	OPA4354AQPWRQ1	
-----------------	----------------	----------------	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com