



Cypress Semiconductor Corporation, 198 Champion Court, San Jose, CA 95134. Tel: (408) 943-2600

PRODUCT TERMINATION NOTIFICATION

PTN: PTN172505B

Date: March 20, 2018

Subject: Addendum to PTN172505A: Product Termination Notification for 90nm Automotive FL1-K NOR Flash Products

Product Obsolescence Information:

The purpose of Addendum B is to extend the LTB and LTS dates for the Automotive FL-1K NOR Flash Marketing Part Numbers due to continued support from our supplier. Seventeen (17) FL1-K marketing part numbers have been added and eight (8) customer specific PPAP FL1-K marketing part numbers have been removed from PTN172505A.

The purpose of Addendum A was to add twelve (12) FL1-K marketing part numbers to the affected parts list of PTN172505.

Cypress announced the obsolescence of select NOR Flash products from its portfolio following an internal review and business decision to discontinue support. The affected part numbers are listed in the attached 'Affected Parts List' file. Last Time Buy (LTB) and Last Time Ship (LTS) dates are provided for each product. The LTB date denotes the last day on which orders will be accepted; these orders may be scheduled for shipment through the LTS date provided.

The parts listed as the "Drop-In Replacement" are form, fit, and core functionality compatible.

The application note attached with this notice is to assist customers with migration from FL-1K products to FL-L products.

Part Numbers Affected: 89

Please see the attached 'Affected Parts List' file for a list of affected part numbers, Last Time Buy dates and Last Time Ship dates.

Qualification Status:

Replacement devices have been previously qualified, unless specifically noted.

Sample Status:

Samples of replacement and substitute products shown in the attachment are available. Please contact your local sales representative to place sample requests.

Approximate Implementation Date:

This change is effective with this notification. See attached listing for specified Last Time Buy and Last Time Ship dates by device.

Response Required:

No response required. For additional information regarding this notice, contact your local sales representative or contact PCN Administrator at pcn_adm@cypress.com.

Please contact your local sales representative if you need assistance with replacement product options or Sai Prashanth Dhanraj at sai.dhanraj@cypress.com.

Sincerely,

Cypress PCN Administration

Item	Marketing Part Number	Last Time Buy Date	Drop-in Replacement	Next Best Alternative
1	315-1345-000 AAA	30-Jun-19	S25FL064LABMFB013	None
2	520966231076	30-Jun-19	None	S25FL064LABMFA013
3	S25FL116K0XMFA010	30-Jun-19	None	S25FL064LABMFA010
4	S25FL116K0XMFA011	30-Jun-19	None	S25FL064LABMFA011
5	S25FL116K0XMFA013	30-Jun-19	None	S25FL064LABMFA013
6	S25FL116K0XMFA040	30-Jun-19	None	S25FL064LABMFA010
7	S25FL116K0XMFA041	30-Jun-19	None	S25FL064LABMFA011
8	S25FL116K0XMFA043	30-Jun-19	None	S25FL064LABMFA013
9	S25FL116K0XMFB040	30-Jun-19	None	S25FL064LABMFB010
10	S25FL116K0XNFA010	30-Jun-19	None	S25FL064LABNFA010
11	S25FL116K0XNFA013	30-Jun-19	None	S25FL064LABNFA013
12	S25FL116K0XNFB010	30-Jun-19	None	S25FL064LABNFB010
13	S25FL116K0XNFB013	30-Jun-19	None	S25FL064LABNFB013
14	S25FL132K0XBHA020	30-Jun-19	None	S25FL064LABBHA020
15	S25FL132K0XBHB023	30-Jun-19	None	S25FL064LABBHB023
16	S25FL132K0XMFA010	30-Jun-19	None	S25FL064LABMFA010
17	S25FL132K0XMFA011	30-Jun-19	None	S25FL064LABMFA011
18	S25FL132K0XMFA013	30-Jun-19	None	S25FL064LABMFA013
19	S25FL132K0XMFB010	30-Jun-19	None	S25FL064LABMFB010
20	S25FL132K0XMFB011	30-Jun-19	None	S25FL064LABMFB011
21	S25FL132K0XMFB040	30-Jun-19	None	S25FL064LABMFB010
22	S25FL132K0XMFB041	30-Jun-19	None	S25FL064LABMFB011
23	S25FL132K0XMFB043	30-Jun-19	None	S25FL064LABMFB013
24	S25FL132K0XNFA010	30-Jun-19	None	S25FL064LABNFA010
25	S25FL132K0XNFA013	30-Jun-19	None	S25FL064LABNFA013
26	S25FL132K0XNFB010	30-Jun-19	None	S25FL064LABNFB010
27	S25FL164K0XMFA000	30-Jun-19	S25FL064LABMFA000	None
28	S25FL164K0XMFA001	30-Jun-19	S25FL064LABMFA001	None
29	S25FL164K0XMFA003	30-Jun-19	S25FL064LABMFA003	None
30	S25FL164K0XMFA010	30-Jun-19	S25FL064LABMFA010	None
31	S25FL164K0XMFA011	30-Jun-19	S25FL064LABMFA011	None
32	S25FL164K0XMFB000	30-Jun-19	S25FL064LABMFB000	None
33	S25FL164K0XMFB003	30-Jun-19	S25FL064LABMFB003	None
34	S25FL164K0XMFB010	30-Jun-19	S25FL064LABMFB010	None
35	S25FL164K0XMFB011	30-Jun-19	S25FL064LABMFB011	None
36	S25FL164K0XMFB013	30-Jun-19	S25FL064LABMFB013	None
37	S25FL164K0XMFBQ10	30-Jun-19	S25FL064LABMFB010	None
38	S25FL164K0XNFA010	30-Jun-19	S25FL064LABNFA010	None
39	S99FL116K0001 P	30-Jun-19	None	S25FL064LABMFB010
40	S99FL132KMM43	30-Jun-19	None	S25FL064LABMFM013
41	S99FL164KMM10	30-Jun-19	S25FL064LABMFM010	None
42	S99FL164KMM13	30-Jun-19	S25FL064LABMFM013	None
43	VLK-580940331	30-Jun-19	S25FL064LABBHB023	None

44	S25FL116K0XBHB030	30-Jun-19	None	S25FL064LABBHB030
45	S25FL116K0XMFB041	30-Jun-19	None	S25FL064LABMFB011
46	S25FL116K0XMFB043	30-Jun-19	None	S25FL064LABMFB013
47	S25FL132K0XNFB040	30-Jun-19	None	S25FL064LABNFB040
48	S25FL164K0XBHB023	30-Jun-19	S25FL064LABBHB023	None
49	S25FL164K0XMFA013	30-Jun-19	S25FL064LABMFA013	None
50	S25FL164K0XMFBQ13	30-Jun-19	S25FL064LABMFB013	None
51	S25FL164K0XNFA011	30-Jun-19	S25FL064LABNFA011	None
52	S25FL164K0XNFA013	30-Jun-19	S25FL064LABNFA013	None
53	S99FL132KMM40	30-Jun-19	None	S25FL064LABMFM010
54	S99FL132KMM41	30-Jun-19	None	S25FL064LABMFM011
55	S99FL164KMM11	30-Jun-19	S25FL064LABMFM011	None
56	S25FL132K0XBHB020	30-Jun-19	None	S25FL064LABBHB020
57	051FL164K0XMFI010	30-Jun-19	S25FL064LABMFA010	None
58	0791076239RQA00	30-Jun-19	None	S25FL064LABMFB010
59	0791078169RQA00	30-Jun-19	S25FL064LABMFB000	None
60	3015357	30-Jun-19	None	S25FL064LABMFB010
61	811600-73670880	30-Jun-19	None	S25FL064LABMFA010
62	C08-0586-0001-0	30-Jun-19	S25FL064LABMFB013	None
63	S99FL132KMN4	30-Jun-19	None	S25FL064LABMFM010
64	S99FL164KMN13	30-Jun-19	S25FL064LABMFM010	None
65	520966231136	30-Jun-19	S25FL064LABMFB013	None
66	520966231496	30-Jun-19	None	S25FL064LABMFA013
67	28294110 D	30-Jun-19	None	S25FL064LABMFB013
68	28450379 A	30-Jun-19	None	S25FL064LABMFB013
69	315-1345-000	30-Jun-19	S25FL064LABMFB013	None
70	568.005.011	30-Jun-19	S25FL164K0XNFA011	None
71	568.262.011	30-Jun-19	S25FL064LABMFB013	None
72	625432-0030 03	30-Jun-19	None	S25FL064LABMFM013
73	751205-0010 01	30-Jun-19	S25FL064LABMFM013	None
74	792.487-00	30-Jun-19	None	S25FL064LABMFA013
75	793.846-00	30-Jun-19	S25FL064LABMFM013	None
76	CATH-4878204	30-Jun-19	None	S25FL064LABMFA013
77	E11043000	30-Jun-19	None	S25FL064LABNFB043
78	S99-50423 P	30-Jun-19	S25FL064LABMFA010	None
79	SX-3130-1658	30-Jun-19	None	S25FL064LABMFB010
80	S25FL116K0XMFB013	30-Jun-19	None	S25FL064LABMFB013
81	S25FL132K0XMFB013	30-Jun-19	None	S25FL064LABMFB013
82	51-02471V01-A			
83	51-30259Z01-A			
84	51-30259Z02-A			
85	51-32598Z01-A			
86	10324-05610			
87	10324-06850			
88	S99FL116K0002 P			
89	S99FL164KM001			