



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000860

DATE: 02-Sep-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX31785ETL+T	N/A			Part reactivated from prior notice: M000857
Discontinuance	DS3644EVKIT#	DS3640K	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	DS3645K	N/A	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	MAX16833CAUE/V+TC0	N/A	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX16833FAUE/V+TC0	N/A	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX20051AUD/V+CLQ	MAX20051AUD/V+	02-Sep-2018	04-Mar-2019	The part was not released
Discontinuance	MAX20051AUD/V+TCLQ	MAX20051AUD/V+T	02-Sep-2018	04-Mar-2019	The part was not released
Discontinuance	MAX20064AUD/V+	N/A	02-Sep-2018	04-Mar-2019	The part was not released
Discontinuance	MAX20064EVKIT#	N/A	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	MAX2135AE/W+C76	MAX2135AE/W+CL8	02-Sep-2017	02-Sep-2017	Leaded with a Lead-Free or RoHS Replacement
Discontinuance	MAX2135AETN+	MAX2135AETN/V+	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX2135AETN+T	MAX2135AETN/V+T	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX32555-LND+	MAX32555-LNS+	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX9508ATE+	N/A	02-Sep-2017	02-Sep-2017	Part can no longer be manufactured
Discontinuance	MAX9508EVKIT	N/A	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	MAX9591ETU+	N/A	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX9591ETU+T	N/A	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX9591EVKIT+	N/A	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	MAX9643EVKIT#	N/A	02-Sep-2017	02-Sep-2017	EVKIT is No Longer Supported
Discontinuance	MAX9665ETP+	N/A	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured
Discontinuance	SD220+T	SD220+123T	02-Sep-2018	04-Mar-2019	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 03-Oct-2017