



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000785

DATE: 14-Oct-2014

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS2175+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	806-0712-20-T	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	806-0712-21-T	806-0712-21+T	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	DS1123LE-100+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1123LE-25+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1123LE-50+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2102 DICE	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2141AQ	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2141AQ+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2143Q+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2143QN+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2165Q	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2165Q+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2165QN+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2176+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2176Q+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2176QN	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2181AQ+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2181AQ+T&R	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS21Q43AT+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS3170DK	N/A	14-Oct-2014	15-Oct-2016	The eval kit is no longer supported
Discontinuance	DS3170N	DS3177N+	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS3170N+T&R	DS3177N+T	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS33M30N+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	ICL7650MJD/HR	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX331HAUK/GG8	MAX9647AUK+T	17-Apr-2015	15-Oct-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Nov-2014

Discontinuance	LMX393AKA+	MAX9092AKA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393AKA+T	MAX9092AKA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393AKA-T	MAX9092AKA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393AUA+	MAX9092AUA+	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393AUA+T	MAX9092AUA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393HAKA+	MAX9092AKA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393HAKA+T	MAX9092AKA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393HAUA+	MAX9092AUA+	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX12005ETM+CF7	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX15301ETJ+CCB	MAX15301AD00+CJF	14-Oct-2014	15-Oct-2016	The part was not released
Discontinuance	MAX15301ETJ+TCCB	MAX15301AD00+CJF	14-Oct-2014	15-Oct-2016	The part was not released
Discontinuance	MAX1935ETA-T	MAX1935ETA+T	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX24001TL+TW	MAX24001TL+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX24002TL+TW	MAX24002TL+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3286CHJ	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3299CUE+	MAX3735AETG+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3634ETM	MAX3634ETM+	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3665EUA	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX3740AETG	MAX3740AETG+	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX3804EVKIT	MAX3804EVKIT#	14-Oct-2014	15-Oct-2016	The eval kit is no longer supported
Discontinuance	MAX3875E/D	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX472ESA/R60330	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX5491WA30000	MAX5491WA30000+	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX5528GTA+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX7234AFIJL	N/A	14-Oct-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX77525QEWI+	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX77609EWJ+T	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX77871EWM+	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX8964EWJ+	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9126EUE	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9164ESD	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9485EUP+T	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX98357EVSYS#TQ	MAX98357EVSYS#TQFN	14-Oct-2014	15-Oct-2016	The eval kit is no longer supported
Discontinuance	MAX9952FCCB+D	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9955BDCCB+D	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9969BDCCQ+D	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Nov-2014

Discontinuance	MAXQ2000-RAX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2000-RBX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2000-RFX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2010-RFX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MX565ASD/M40165	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MX7545AUQ/883B	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	VSC7161XHK	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	5962-8876402LA	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS1123LE-200+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2143Q	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2165Q+T&R	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS2181A+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS3170+	DS3177+	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS3170N+	DS3177N+	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	DS3253N+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	LMX393HAUA+T	MAX9092AUA+T	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX162CMRG/HR	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX4233ABC+G45	MAX4233ABC+T	17-Apr-2015	15-Oct-2016	Special No Longer Needed
Discontinuance	MAX5491SC03200	MAX5491SC03200+	17-Apr-2015	15-Oct-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	MAX77609EWJ+	N/A	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX8884YEREKE+	MAX8884ZEREKE+	14-Oct-2014	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9320EVKIT	N/A	14-Oct-2014	15-Oct-2016	The eval kit is no longer supported
Discontinuance	MAX9952DCCB+D	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2000-QAX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX9952DCCB+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAX4233ABC+TG45	MAX4233ABC+T	17-Apr-2015	15-Oct-2016	Special No Longer Needed
Discontinuance	MAX238MRG/883B	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2000-QBX+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured
Discontinuance	MAXQ2010-KIT#	N/A	14-Oct-2014	15-Oct-2016	The eval kit is no longer supported
Discontinuance	DS3182+	N/A	17-Apr-2015	15-Oct-2016	Part can no longer be manufactured