



Micron Technology, Inc.
8000 S. Federal Way
PO Box 6
Boise, ID United States

J96R v5.0 and v5.1 are End of Life

PCN: 32347

Published: 2017-05-24

| | |
|--------------------------|--|
| Type: | End of Life |
| Description: | Micron's J96R (16GB + 16Gb) eMCP are going End of Life |
| Reason: | Better Align With Industry Standard |
| Product Affected: | J96R (16GB + 16Gb) v5.0 and v5.1 |

| Affected Micron Part Number | Recommended Replacement | Customer Part Number |
|------------------------------------|--------------------------------|-----------------------------|
| <u>Component</u> | | |
| MT29TZZZ5D6EKFRL-107 W.96R | MT29TZZZ5D6DKFRL-107 W.9A6 | |
| MT29TZZZ5D6JKFRL-107 W.96R | MT29TZZZ5D6DKFRL-107 W.9A6 | |

*Materials that have been ordered are in **bold**.

| | |
|----------------------------------|-----------------------|
| Method of Identification: | Marketing Part Number |
| Micron Sites Affected: | All Sites |
| Sample Available: | 2017-05-19 |
| Last Purchase Date*: | 2017-11-24 |
| Last Shipment Date: | 2018-05-24 |

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.