



Product Change Notification

TE Connectivity

Product Change Notification: P-18-015849

PCN Date: 21-MAY-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

MSR relay series (version with AgCdO contact)

Description of Changes

The following part numbers are being obsoleted (obsolete status). A last time buy opportunity is provided as per the dates stated thereafter. Proposed alternative types of relay are offered in attached file. Please note that new conditions may apply, please contact your local customer sales representative for inquiries.

Other attachments:

[MSR substitution list](#)

Reason for Changes:

Part status change. Discontinuance. Dear Customer, You are receiving this notification because TE Connectivity has record of you purchasing a part or multiple parts on the list below. According to RoHS restrictions cadmium is only allowed to be used per an exception which is currently in discussion to be expired. In this situation first suppliers stop production of AgCdO contacts. To avoid short term decisions due to updated RoHS restrictions or due to supply problems of AgCdO we decided about regular discontinuance of the part numbers mentioned in this PCN. Well proved RoHS conform alternatives are available.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
31-DEC-2018	
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
30-JUN-2019	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393223-2	YES			"V23061B1006A401"			
1-1393223-5	YES			"V23061B1006A601"			
1393222-5	YES			"V23061A1002A402"			
1393223-3	YES			"T75S5D112-12", "V23061B1005X 6"			
2-1393222-3	YES			"V23061A1005A402", "CA1475-000", "AMPS-2-1393222-3"			
2-1393223-1	YES			"V23061B1007A401"			
2-1393223-8	YES			"T75S5D112-24", "V23061B1007X 8"			
3-1393223-8	YES			"V23061B1009A401"			
4-1393222-2	YES			"V23061A1007A402"			
4-1393223-1	YES			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			
7-1393222-5	YES			"V23061B1002A601"			
7-1393222-6	YES			"T75S5D112-05", "V23061B1002X 3"			
8-1393222-6	YES			"V23061B1004A401"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393223-2	YES			"V23061B1006A401"			
1-1393223-5	YES			"V23061B1006A601"			
1393222-5	YES			"V23061A1002A402"			
1393223-3	YES			"T75S5D112-12", "V23061B1005X 6"			
2-1393222-3	YES			"V23061A1005A402", "CA1475-000", "AMPS-2-1393222-3"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393223-1	YES			"V23061B1007A401"			
2-1393223-8	YES			"T75S5D112-24", "V23061B1007X 8"			
3-1393223-8	YES			"V23061B1009A401"			
4-1393222-2	YES			"V23061A1007A402"			
7-1393222-5	YES			"V23061B1002A601"			
8-1393222-6	YES			"V23061B1004A401"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393223-2	YES			"V23061B1006A401"			
1-1393223-5	YES			"V23061B1006A601"			
1393222-5	YES			"V23061A1002A402"			
1393223-3	YES			"T75S5D112-12", "V23061B1005X 6"			
2-1393222-3	YES			"V23061A1005A402", "CA1475-000", "AMPS-2-1393222-3"			
2-1393223-1	YES			"V23061B1007A401"			
2-1393223-8	YES			"T75S5D112-24", "V23061B1007X 8"			
3-1393223-8	YES			"V23061B1009A401"			
4-1393222-2	YES			"V23061A1007A402"			
4-1393223-1	YES			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			
7-1393222-5	YES			"V23061B1002A601"			
8-1393222-6	YES			"V23061B1004A401"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393223-3	YES			"T75S5D112-12", "V23061B1005X 6"			
2-1393223-8	YES			"T75S5D112-24", "V23061B1007X 8"			
7-1393222-6	YES			"T75S5D112-05", "V23061B1002X 3"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
4-1393223-1	YES			"T75S5D112-48", "V23061B1009X 10", "V23061B1009X010"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1393223-3	YES			"T75S5D112-12", "V23061B1005X 6"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-1393223-8	YES			"T75S5D112-24", "V23061B1007X 8"			
7-1393222-6	YES			"T75S5D112-05", "V23061B1002X 3"			