



Title of Change:	Changes to former Fairchild Part Numbers containing an 'underscore', replacing with 'dash' (hyphen).
Proposed first ship date:	October 30, , 2017
Contact information:	Contact your local ON Semiconductor Sales Office
Samples:	Not applicable for this change.
Additional Reliability Data:	Not applicable for this change.
Type of notification:	This is a Final Product/Process Change Notification (FPCN) sent to customers. FPCNs are issued 90 days prior to implementation of the change.ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact <PCN.Support@onsemi.com>.
Change Part Identification:	Affected Part Numbers are identified in the attached Affected Part List.
Change category:	<input type="checkbox"/> Wafer Fab Change <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other: Orderable Part Number
Change Sub-Category(s):	<input type="checkbox"/> Manufacturing Site Change/Addition <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Material Change <input type="checkbox"/> Product specific change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Shipping/Packaging/Marking <input checked="" type="checkbox"/> Other: Part Number Change
Sites Affected:	<input type="checkbox"/> All site(s) <input checked="" type="checkbox"/> Not applicable <input type="checkbox"/> ON Semiconductor site(s) <input type="checkbox"/> External Foundry/Subcon site(s) Select site: Select site:
Description and Purpose:	<p>On Semiconductor acquired Fairchild Semiconductor on September 19th, 2016. As part of the integration, it is necessary to change some of the Fairchild orderable part numbers to meet ON Semiconductor's system requirements. Since the product management systems do not have the ability to manage part nomenclature that utilizes an underscore (_), the underscore (_) in the Fairchild part numbers will be changed to a dash (-).</p> <p>The orderable part numbers that will change are on the Affected Parts List attached to this Product Change Notice.</p> <p>This change will be effective at system integration, which is currently scheduled for Monday, October 30th, 2017. Until that time, customers must continue to order the current part numbers as they do today, through the Fairchild ordering system. More information regarding the October 30th system integration will be provided to customers beginning in July. If customers have questions regarding the system integration please email the questions to Fairchild_questions@onsemi.com</p> <p>ON Semiconductor will be modifying all datasheets associated with the former Fairchild products to incorporate the new orderable part number changes by the PCN effective date.</p>
Reliability Data Summary:	Not applicable for this change.
Electrical Characteristic Summary:	



Not applicable for this change.

Qualification Plan:

Not applicable for this change.



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
0332_B03005A	0332-B03005A
0685_2N7053	0685-2N7053
0785_MMBT2484	0785-MMBT2484
0785_MMBT5089	0785-MMBT5089
1049_B10209A	1049-B10209A
1085_BCX70J	1085-BCX70J
1085_MMBT100A	1085-MMBT100A
1085_PN100A	1085-PN100A
1285_TN3019A	1285-TN3019A
1649_B16063A	1649-B16063A
1685_MMBT5551	1685-MMBT5551
1985_2N2222A	1985-2N2222A
1985_MBT2222A	1985-MBT2222A
1H85_MMBD3070	1H85-MMBD3070
1L85_D1L001A	1L85-D1L001A
1L85_MMBD3595	1L85-MMBD3595
1L85_MMBD459A	1L85-MMBD459A
1MD2_FD3369C	1MD2-FDH3369C
1N4148_T26A	1N4148-T26A
1N4148_T50A	1N4148-T50A
1N4148_T50R	1N4148-T50R
1N459_T50R	1N459-T50R
1N4728A_T50A	1N4728A-T50A
1N4730A_T50A	1N4730A-T50A
1N4731A_T50A	1N4731A-T50A
1N4732A_T50A	1N4732A-T50A
1N4733A_T50A	1N4733A-T50A
1N4733A_T50R	1N4733A-T50R
1N4734ATR_F153	1N4734ATR-F153
1N4734A_T50A	1N4734A-T50A
1N4734A_T50R	1N4734A-T50R
1N4735A_T50A	1N4735A-T50A
1N4735A_T50R	1N4735A-T50R
1N4736A_T50A	1N4736A-T50A
1N4736A_T50R	1N4736A-T50R
1N4737A_T50A	1N4737A-T50A
1N4738A_T50A	1N4738A-T50A
1N4738A_T50R	1N4738A-T50R
1N4739A_T50A	1N4739A-T50A
1N4740A_T50A	1N4740A-T50A



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
1N4741A_T50A	1N4741A-T50A
1N4742A_T50A	1N4742A-T50A
1N4743A_T50A	1N4743A-T50A
1N4743A_T50R	1N4743A-T50R
1N4744A_T50A	1N4744A-T50A
1N4744A_T50R	1N4744A-T50R
1N4745A_T50A	1N4745A-T50A
1N4746A_T50A	1N4746A-T50A
1N4747A_T50A	1N4747A-T50A
1N4748A_T50A	1N4748A-T50A
1N4749A_T50A	1N4749A-T50A
1N4749A_T50R	1N4749A-T50R
1N4750A_T50A	1N4750A-T50A
1N4751A_T50A	1N4751A-T50A
1N4752A_T50A	1N4752A-T50A
1N4753A_T50A	1N4753A-T50A
1N4754A_T50A	1N4754A-T50A
1N4755A_T50A	1N4755A-T50A
1N4758A_T50A	1N4758A-T50A
1N486B_T50A	1N486B-T50A
1N5260B_T50A	1N5260B-T50A
1N5262B_T50A	1N5262B-T50A
1N5263B_T50R	1N5263B-T50R
1N914_T50A	1N914-T50A
1P85_D1P001D	1P85-D1P001D
1P85_MMBD4148	1P85-MMBD4148
1P85_MMBD4448	1P85-MMBD4448
2185_MBT2369A	2185-MBT2369A
2385_MMBT3904	2385-MMBT3904
2G49_B2G005A	2G49-B2G005A
2K49_B2K002A	2K49-B2K002A
2N7000TA_T	2N7000TA-T
2N7000_D26Z	2N7000-D26Z
2N7000_D74Z	2N7000-D74Z
2N7000_D75Z	2N7000-D75Z
2N7002DW_G	2N7002DW-G
2N7002_D87Z	2N7002-D87Z
2N7002_F169	2N7002-F169
2N7002_G	2N7002-G
2N7002_TG	2N7002-TG



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
2V85_BAV23S	2V85-BAV23S
3985_D39054A	3985-D39054A
3G49_B3G005A	3G49-B3G005A
3V86_D3V004A	3V86-D3V004A
4085_2N2857	4085-2N2857
4249_NB42102E	4249-NB42102E
4249_NB42112B	4249-NB42112B
4285_2N2857	4285-2N2857
4785_BF240	4785-BF240
4885_MPSA42	4885-MPSA42
495220TU_SN00236	495220TU-SN00236
4E85_BSS84	4E85-BSS84
4Q85_D44H11	4Q85-D44H11
5085_2N4416A	5085-2N4416A
5085_MMBF5485	5085-MMBF5485
5149_NB51374B	5149-NB51374B
5185_2N4392	5185-2N4392
5185_2N4393	5185-2N4393
5249_B52069B	5249-B52069B
5285_MMBFJ201	5285-MMBFJ201
5385_MMBF4117	5385-MMBF4117
5385_MMBF4119	5385-MMBF4119
5449_NB54014	5449-NB54014
5449_NB54015	5449-NB54015
5885_2N5434	5885-2N5434
5985_J105	5985-J105
5Q37_W5Q011D	5Q37-W5Q011D
5Q85_D45H11	5Q85-D45H11
6385_2N2907A	6385-2N2907A
6385_MBT2907A	6385-MBT2907A
6549_NB65115	6549-NB65115
6585_2N4209	6585-2N4209
6685_2N3906	6685-2N3906
6685_MMBT3906	6685-MMBT3906
6686_2N3906	6686-2N3906
6686_CL66299A	6686-CL66299A
6785_2N4033	6785-2N4033
6785_TN4033A	6785-TN4033A
6885_BC556B	6885-BC556B
6985_BC556B	6985-BC556B



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
6PT85_2N7002	6PT85-2N7002
7449_B74043A	7449-B74043A
7485_MMBT5401	7485-MMBT5401
74AC08SCX_T	74AC08SCX-T
74AC14SCX_X	74AC14SCX-X
74AC14SC_T	74AC14SC-T
74AC32SCX_T	74AC32SCX-T
74AC32SJX_T	74AC32SJX-T
74ACT00SCX_T	74ACT00SCX-T
74ACT08MTCX_T	74ACT08MTCX-T
74LCX06MTCX_T	74LCX06MTCX-T
74LCX08MTCX_T	74LCX08MTCX-T
74LCX08MX_T	74LCX08MX-T
74LCX08SJX_T	74LCX08SJX-T
74LCX125MTCX_T	74LCX125MTCX-T
74LCX14MTCX_T	74LCX14MTCX-T
74LCX16244MTDX_T	74LCX16244MTDX-T
74LCX16245MTDX_T	74LCX16245MTDX-T
74LCX240SJX_T	74LCX240SJX-T
74LCX244MTCX_T	74LCX244MTCX-T
74LCX245MTCX_T	74LCX245MTCX-T
74LCX373MTCX_T	74LCX373MTCX-T
74LCX38MTCX_T	74LCX38MTCX-T
74LCX74MTCX_T	74LCX74MTCX-T
74LCX86MTCX_T	74LCX86MTCX-T
74LVT245MTCX_T	74LVT245MTCX-T
74LVX125SJX_T	74LVX125SJX-T
74VCX08MTCX_T	74VCX08MTCX-T
74VCX16244MTDX_T	74VCX16244MTDX-T
74VHC00MTCX_T	74VHC00MTCX-T
74VHC02MTCX_SF500910	74VHC02MTCX-SF500910
74VHC02MTCX_TF500910	74VHC02MTCX-TF500910
74VHC02MTCX_XF500910	74VHC02MTCX-XF500910
74VHC08MTCX_SF500909	74VHC08MTCX-SF500909
74VHC08MTCX_TF500909	74VHC08MTCX-TF500909
74VHC08MTCX_XF500909	74VHC08MTCX-XF500909
74VHC123AMX_T	74VHC123AMX-T
74VHC125MTCX_T	74VHC125MTCX-T
74VHC132MX_T	74VHC132MX-T
74VHC14MTCX_SF500908	74VHC14MTCX-SF500908



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
74VHC14MTCX_T	74VHC14MTCX-T
74VHC14MTCX_TF500908	74VHC14MTCX-TF500908
74VHC14MTCX_XF500908	74VHC14MTCX-XF500908
74VHC374MTCX_T	74VHC374MTCX-T
74VHC573MTCX_T	74VHC573MTCX-T
74VHC595MTCX_T	74VHC595MTCX-T
74VHC74MTCX_SF500950	74VHC74MTCX-SF500950
74VHC74MTCX_T	74VHC74MTCX-T
74VHC74MTCX_TF500950	74VHC74MTCX-TF500950
74VHC74MTCX_XF500950	74VHC74MTCX-XF500950
74VHCT541AMTCX_T	74VHCT541AMTCX-T
7585_MMBTH81	7585-MMBTH81
7585_P75004A	7585-P75004A
7685_MMBTA92	7685-MMBTA92
864001_281W	864001-281W
868324_001W	868324-001W
868325_001W	868325-001W
868326_001W	868326-001W
868327_001W	868327-001W
9285_MMBFJ309	9285-MMBFJ309
9285_MMBFJ310	9285-MMBFJ310
9G85_BSS138	9G85-BSS138
9GA85_2N7000	9GA85-2N7000
9V49_NB9V004	9V49-NB9V004
BAS16_D87Z	BAS16-D87Z
BAS31_D87Z	BAS31-D87Z
BAT54A_F165	BAT54A-F165
BAT54S_D87Z	BAT54S-D87Z
BAT54S_NBKA001	BAT54S-NBKA001
BAT54_D87Z	BAT54-D87Z
BAV103_G	BAV103-G
BAV21_T50A	BAV21-T50A
BAV21_T50R	BAV21-T50R
BAV99_D87Z	BAV99-D87Z
BAV99_F165	BAV99-F165
BAW74_D87Z	BAW74-D87Z
BC516_D27Z	BC516-D27Z
BC517_D74Z	BC517-D74Z
BC63916_D27Z	BC63916-D27Z
BC63916_D74Z	BC63916-D74Z



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
BCV27_SN00397	BCV27-SN00397
BCW68G_SN00381	BCW68G-SN00381
BD13910STU_T	BD13910STU-T
BD13910STU_X	BD13910STU-X
BD14016STU_T	BD14016STU-T
BS170_D26Z	BS170-D26Z
BS170_D27Z	BS170-D27Z
BS170_D74Z	BS170-D74Z
BS170_D75Z	BS170-D75Z
BS170_T	BS170-T
BS270_D74Z	BS270-D74Z
BSS123_F169	BSS123-F169
BSS123_G	BSS123-G
BSS123_T	BSS123-T
BSS138_D87Z	BSS138-D87Z
BSS138_F085	BSS138-F085
BSS138_F169	BSS138-F169
BSS138_G	BSS138-G
BSS138_SB9G001	BSS138-SB9G001
BSS138_SB9G001P	BSS138-SB9G001P
BSS138_T	BSS138-T
BSS138_TG	BSS138-TG
BSS84_F169	BSS84-F169
BSS84_G	BSS84-G
BSS84_T	BSS84-T
BU406TU_T	BU406TU-T
BUZ11_NR4941	BUZ11-NR4941
BZX79C10_T50A	BZX79C10-T50A
BZX79C11_T50A	BZX79C11-T50A
BZX79C12_T50A	BZX79C12-T50A
BZX79C13_T50A	BZX79C13-T50A
BZX79C15_T50A	BZX79C15-T50A
BZX79C15_T50R	BZX79C15-T50R
BZX79C16_T50A	BZX79C16-T50A
BZX79C18_T50A	BZX79C18-T50A
BZX79C20_T50A	BZX79C20-T50A
BZX79C24_T50A	BZX79C24-T50A
BZX79C27_T50A	BZX79C27-T50A
BZX79C2V4_T50A	BZX79C2V4-T50A
BZX79C2V7_T50A	BZX79C2V7-T50A



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
BZX79C30_T50A	BZX79C30-T50A
BZX79C33_T50A	BZX79C33-T50A
BZX79C36_T50A	BZX79C36-T50A
BZX79C39_T50A	BZX79C39-T50A
BZX79C3V3_T50A	BZX79C3V3-T50A
BZX79C3V6_T50A	BZX79C3V6-T50A
BZX79C3V9_T50A	BZX79C3V9-T50A
BZX79C4V3_T50A	BZX79C4V3-T50A
BZX79C4V7_T50A	BZX79C4V7-T50A
BZX79C51_T50A	BZX79C51-T50A
BZX79C5V1_T50A	BZX79C5V1-T50A
BZX79C5V6_T50A	BZX79C5V6-T50A
BZX79C6V2_T50A	BZX79C6V2-T50A
BZX79C6V2_T50R	BZX79C6V2-T50R
BZX79C6V8_T50A	BZX79C6V8-T50A
BZX79C7V5_T50A	BZX79C7V5-T50A
BZX79C8V2_T50A	BZX79C8V2-T50A
BZX79C9V1_T50A	BZX79C9V1-T50A
BZX85C10_T50A	BZX85C10-T50A
BZX85C10_T50R	BZX85C10-T50R
BZX85C12_T50A	BZX85C12-T50A
BZX85C12_T50R	BZX85C12-T50R
BZX85C13_T50A	BZX85C13-T50A
BZX85C15_T50A	BZX85C15-T50A
BZX85C15_T50R	BZX85C15-T50R
BZX85C16_T50A	BZX85C16-T50A
BZX85C18_T50A	BZX85C18-T50A
BZX85C18_T50R	BZX85C18-T50R
BZX85C24_T50R	BZX85C24-T50R
BZX85C36_T50R	BZX85C36-T50R
BZX85C51_T50A	BZX85C51-T50A
BZX85C5V1_T50A	BZX85C5V1-T50A
BZX85C5V6_T50R	BZX85C5V6-T50R
BZX85C6V2_T50A	BZX85C6V2-T50A
BZX85C7V5_T50A	BZX85C7V5-T50A
D3D7_FD6308C	D3D7-FD6308C
ES1B_F080	ES1B-F080
ES1D_F080	ES1D-F080
ES85_84C4V7	ES85-84C4V7
FAB3103UCX_T	FAB3103UCX-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FAN1100_F085	FAN1100-F085
FAN1100_SN00350	FAN1100-SN00350
FAN1101A_F085	FAN1101A-F085
FAN1101A_SN00352	FAN1101A-SN00352
FAN1101B_SN00352	FAN1101B-SN00352
FAN1102_SN00398	FAN1102-SN00398
FAN1110_SN00351	FAN1110-SN00351
FAN156L6X_F106	FAN156L6X-F106
FAN1852MX_SN00164	FAN1852MX-SN00164
FAN2106MPX_T	FAN2106MPX-T
FAN21SV06EMPX_Z	FAN21SV06EMPX-Z
FAN256L8X_F106	FAN256L8X-F106
FAN301HLMY_F116	FAN301HLMY-F116
FAN301ULMY_SN00338	FAN301ULMY-SN00338
FAN302HLMY_F117	FAN302HLMY-F117
FAN3100TMPX_T	FAN3100TMPX-T
FAN3121CMX_F085	FAN3121CMX-F085
FAN3121TMX_F085	FAN3121TMX-F085
FAN3122CMX_F085	FAN3122CMX-F085
FAN3122TMX_F085	FAN3122TMX-F085
FAN3213TMX_F085	FAN3213TMX-F085
FAN3214TMX_F085	FAN3214TMX-F085
FAN3216TMX_F085	FAN3216TMX-F085
FAN3217TMX_F085	FAN3217TMX-F085
FAN3223CMX_F085	FAN3223CMX-F085
FAN3223TMX_F085	FAN3223TMX-F085
FAN3224CMX_F085	FAN3224CMX-F085
FAN3224TMX_F085	FAN3224TMX-F085
FAN3224TUMX_F085	FAN3224TUMX-F085
FAN3225CMX_F085	FAN3225CMX-F085
FAN3225TMX_F085	FAN3225TMX-F085
FAN3226CMX_F085	FAN3226CMX-F085
FAN3226TMX_F085	FAN3226TMX-F085
FAN3227CMX_F085	FAN3227CMX-F085
FAN3227TMX_F085	FAN3227TMX-F085
FAN3228CMX_F085	FAN3228CMX-F085
FAN3228TMX_F085	FAN3228TMX-F085
FAN3229CMX_F085	FAN3229CMX-F085
FAN3229TMX_F085	FAN3229TMX-F085
FAN3268TMX_F085	FAN3268TMX-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FAN3988IL6X_F113	FAN3988IL6X-F113
FAN3988IL6X_T	FAN3988IL6X-T
FAN4010IL6X_F113	FAN4010IL6X-F113
FAN4274IMU8X_G	FAN4274IMU8X-G
FAN4800ASMY_F116	FAN4800ASMY-F116
FAN48623UC35X_SN00380	FAN48623UC35X-SN00380
FAN48630UC315X_T	FAN48630UC315X-T
FAN48632UC33X_T	FAN48632UC33X-T
FAN5234MTCX_T	FAN5234MTCX-T
FAN5236MTCX_NA3C246	FAN5236MTCX-NA3C246
FAN5341UMPX_F106	FAN5341UMPX-F106
FAN53501AUCX_P	FAN53501AUCX-P
FAN53501AUCX_T	FAN53501AUCX-T
FAN53555UC05X_T	FAN53555UC05X-T
FAN53555UC08X_T	FAN53555UC08X-T
FAN5355UC03X_T	FAN5355UC03X-T
FAN5355UC08X_T	FAN5355UC08X-T
FAN53601UC182X_P	FAN53601UC182X-P
FAN53611AUC123X_SN00387	FAN53611AUC123X-SN00387
FAN5362UC29X_T	FAN5362UC29X-T
FAN5365UC00X_T	FAN5365UC00X-T
FAN5402UCX_T	FAN5402UCX-T
FAN5403BUCX_T	FAN5403BUCX-T
FAN54046UCX_T	FAN54046UCX-T
FAN5903BUCX_T	FAN5903BUCX-T
FAN5904BUC01X_T	FAN5904BUC01X-T
FAN6111MPX_F116	FAN6111MPX-F116
FAN6224M_T	FAN6224M-T
FAN6754AMRM_T	FAN6754AMRM-T
FAN6754BMLM_T	FAN6754BMLM-T
FAN6754MRM_F116	FAN6754MRM-F116
FAN6863TY_SN00257	FAN6863TY-SN00257
FAN7080MX_GF085	FAN7080MX-GF085
FAN7080MX_SN00333	FAN7080MX-SN00333
FAN7080MX_TGF085	FAN7080MX-TGF085
FAN7080M_GF085	FAN7080M-GF085
FAN7081MX_GF085	FAN7081MX-GF085
FAN7081MX_SN00035	FAN7081MX-SN00035
FAN7081M_GF085	FAN7081M-GF085
FAN7083MX_GF085	FAN7083MX-GF085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FAN7083MX_SN00037	FAN7083MX-SN00037
FAN7083M_GF085	FAN7083M-GF085
FAN7085MX_GF085	FAN7085MX-GF085
FAN7085M_GF085	FAN7085M-GF085
FAN7093_F085	FAN7093-F085
FAN7171MX_F085	FAN7171MX-F085
FAN7171MX_F085P	FAN7171MX-F085P
FAN7171M_F085	FAN7171M-F085
FAN7190MX_F085	FAN7190MX-F085
FAN7190MX_F085P	FAN7190MX-F085P
FAN7190M_F085	FAN7190M-F085
FAN7191MX_F085	FAN7191MX-F085
FAN73611MX_OP	FAN73611MX-OP
FAN7380MX_G	FAN7380MX-G
FAN7380MX_OP	FAN7380MX-OP
FAN7380MX_WS	FAN7380MX-WS
FAN7382M1X_F172	FAN7382M1X-F172
FAN7382MX_G	FAN7382MX-G
FAN7382MX_WS	FAN7382MX-WS
FAN73832MX_T	FAN73832MX-T
FAN7383MX_WS	FAN7383MX-WS
FAN7930BMX_F172	FAN7930BMX-F172
FAN7930BMX_F172G	FAN7930BMX-F172G
FAN7930BMX_G	FAN7930BMX-G
FAN7930CMX_F172G	FAN7930CMX-F172G
FAN7930CMX_G	FAN7930CMX-G
FAN8413MX_G	FAN8413MX-G
FCA20N60S_F109	FCA20N60S-F109
FCA20N60_F109	FCA20N60-F109
FCA47N60F_SN00171	FCA47N60F-SN00171
FCA47N60_F109	FCA47N60-F109
FCB20N60F_F085	FCB20N60F-F085
FCB20N60_F085	FCB20N60-F085
FCD5N60TM_WS	FCD5N60TM-WS
FCD5N60_F085	FCD5N60-F085
FCD7N60TM_WS	FCD7N60TM-WS
FCD900N60Z_SN00303	FCD900N60Z-SN00303
FCH023N65S3_F155	FCH023N65S3-F155
FCH040N65S3_F155	FCH040N65S3-F155
FCH041N60F_F085	FCH041N60F-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FCH041N65EF_F155	FCH041N65EF-F155
FCH041N65F_F085	FCH041N65F-F085
FCH041N65F_F155	FCH041N65F-F155
FCH060N80_F155	FCH060N80-F155
FCH067N65S3_F155	FCH067N65S3-F155
FCH072N60F_F085	FCH072N60F-F085
FCH077N65F_F085	FCH077N65F-F085
FCH077N65F_F155	FCH077N65F-F155
FCH085N80_F155	FCH085N80-F155
FCH104N60F_F085	FCH104N60F-F085
FCH110N65F_F155	FCH110N65F-F155
FCH150N65F_F155	FCH150N65F-F155
FCH190N65F_F085	FCH190N65F-F085
FCH190N65F_F155	FCH190N65F-F155
FCH47N60F_F085	FCH47N60F-F085
FCH47N60F_F133	FCH47N60F-F133
FCH47N60_F085	FCH47N60-F085
FCH47N60_F133	FCH47N60-F133
FCI25N60N_F102	FCI25N60N-F102
FCP11N60N_F102	FCP11N60N-F102
FCP16N60N_F102	FCP16N60N-F102
FCP190N60_GF102	FCP190N60-GF102
FCP22N60N_F102	FCP22N60N-F102
FCP25N60N_F102	FCP25N60N-F102
FCP9N60N_F102	FCP9N60N-F102
FCPF190N60E_F152	FCPF190N60E-F152
FCPF190N60_F152	FCPF190N60-F152
FCPF260N60E_F152	FCPF260N60E-F152
FCPF380N60E_F152	FCPF380N60E-F152
FCPF380N60_F152	FCPF380N60-F152
FCU900N60Z_SN00265	FCU900N60Z-SN00265
FDA16N50_F109	FDA16N50-F109
FDA20N50_F109	FDA20N50-F109
FDB035AN06A0_F085	FDB035AN06A0-F085
FDB035AN06A0_SN00015	FDB035AN06A0-SN00015
FDB045AN08A0_F085	FDB045AN08A0-F085
FDB045AN08A0_SN00237	FDB045AN08A0-SN00237
FDB050AN06A0_SN00269	FDB050AN06A0-SN00269
FDB0690N1507L_SN00376	FDB0690N1507L-SN00376
FDB070AN06A0_F085	FDB070AN06A0-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDB075N15A_F085	FDB075N15A-F085
FDB088N08_F141	FDB088N08-F141
FDB12N50FTM_WS	FDB12N50FTM-WS
FDB14AN06LA0_F085	FDB14AN06LA0-F085
FDB20AN06A0_B82014A	FDB20AN06A0-B82014A
FDB2532_F085	FDB2532-F085
FDB2532_SB82023A	FDB2532-SB82023A
FDB2532_SN00238	FDB2532-SN00238
FDB2552_F085	FDB2552-F085
FDB2552_SB82178	FDB2552-SB82178
FDB3632_F085	FDB3632-F085
FDB3632_F101	FDB3632-F101
FDB3632_SN00239	FDB3632-SN00239
FDB3652_F085	FDB3652-F085
FDB3672_F085	FDB3672-F085
FDB42AN15A0_F085	FDB42AN15A0-F085
FDB42AN15A0_SB82021A	FDB42AN15A0-SB82021A
FDB8030L_F169	FDB8030L-F169
FDB8160_F085	FDB8160-F085
FDB8441_F085	FDB8441-F085
FDB8442_F085	FDB8442-F085
FDB8443_F085	FDB8443-F085
FDB8444_F085	FDB8444-F085
FDB8444_SB82185	FDB8444-SB82185
FDB8444_SB82185P	FDB8444-SB82185P
FDB8444_TSB82185	FDB8444-TSB82185
FDB8445_F085	FDB8445-F085
FDB86360_F085	FDB86360-F085
FDB86363_F085	FDB86363-F085
FDB86366_F085	FDB86366-F085
FDB86563_F085	FDB86563-F085
FDB86566_F085	FDB86566-F085
FDB86569_F085	FDB86569-F085
FDB8832_F085	FDB8832-F085
FDB8860_F085	FDB8860-F085
FDB8870_F085	FDB8870-F085
FDB8896_F085	FDB8896-F085
FDB9403L_F085	FDB9403L-F085
FDB9403_F085	FDB9403-F085
FDB9406L_F085	FDB9406L-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDB9406_F085	FDB9406-F085
FDB9409L_F085	FDB9409L-F085
FDB9409_F085	FDB9409-F085
FDB9503L_F085	FDB9503L-F085
FDBL86062_F085	FDBL86062-F085
FDBL86063_F085	FDBL86063-F085
FDBL86210_F085	FDBL86210-F085
FDBL86361_F085	FDBL86361-F085
FDBL86363_F085	FDBL86363-F085
FDBL86366_F085	FDBL86366-F085
FDBL86561_F085	FDBL86561-F085
FDBL86563_F085	FDBL86563-F085
FDBL86566_F085	FDBL86566-F085
FDBL9401_F085	FDBL9401-F085
FDBL9403_F085	FDBL9403-F085
FDBL9406_F085	FDBL9406-F085
FDBS09H04A_F085A	FDBS09H04A-F085A
FDC2512_F169	FDC2512-F169
FDC2512_P	FDC2512-P
FDC2512_T	FDC2512-T
FDC2612_F169	FDC2612-F169
FDC3512_F169	FDC3512-F169
FDC3535_F169	FDC3535-F169
FDC3601N_SN00322	FDC3601N-SN00322
FDC3612_F169	FDC3612-F169
FDC5612_F169	FDC5612-F169
FDC5612_G	FDC5612-G
FDC5614P_F169	FDC5614P-F169
FDC5614P_G	FDC5614P-G
FDC5614P_T	FDC5614P-T
FDC5614P_X	FDC5614P-X
FDC5661N_F085	FDC5661N-F085
FDC602P_T	FDC602P-T
FDC604P_T	FDC604P-T
FDC606P_G	FDC606P-G
FDC606P_PG	FDC606P-PG
FDC606P_T	FDC606P-T
FDC606P_TG	FDC606P-TG
FDC608PZ_F171	FDC608PZ-F171
FDC610PZ_G	FDC610PZ-G



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDC610PZ_P	FDC610PZ-P
FDC610PZ_PG	FDC610PZ-PG
FDC610PZ_TG	FDC610PZ-TG
FDC6301N_F169	FDC6301N-F169
FDC6301N_F169G	FDC6301N-F169G
FDC6301N_G	FDC6301N-G
FDC6302P_F169	FDC6302P-F169
FDC6303N_T	FDC6303N-T
FDC6304P_F169	FDC6304P-F169
FDC6310P_T	FDC6310P-T
FDC6320C_F169	FDC6320C-F169
FDC6321C_F169	FDC6321C-F169
FDC6323L_F169	FDC6323L-F169
FDC6323L_T	FDC6323L-T
FDC6323L_Z	FDC6323L-Z
FDC6324L_F169	FDC6324L-F169
FDC6324L_Z	FDC6324L-Z
FDC6325L_F169	FDC6325L-F169
FDC6326L_F169	FDC6326L-F169
FDC6326L_Z	FDC6326L-Z
FDC6327C_F169	FDC6327C-F169
FDC6327C_T	FDC6327C-T
FDC6327C_Z	FDC6327C-Z
FDC6329L_F169	FDC6329L-F169
FDC6330L_F169	FDC6330L-F169
FDC6330L_Z	FDC6330L-Z
FDC6331L_G	FDC6331L-G
FDC6331L_T	FDC6331L-T
FDC6331L_TG	FDC6331L-TG
FDC6333C_G	FDC6333C-G
FDC6333C_T	FDC6333C-T
FDC637AN_F169	FDC637AN-F169
FDC637AN_NB5E023A	FDC637AN-NB5E023A
FDC637AN_T	FDC637AN-T
FDC637BNZ_T	FDC637BNZ-T
FDC638APZ_F171	FDC638APZ-F171
FDC638APZ_PSBMS001	FDC638APZ-PSBMS001
FDC638APZ_SBMS001	FDC638APZ-SBMS001
FDC638APZ_SG00288	FDC638APZ-SG00288
FDC638APZ_T	FDC638APZ-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDC638APZ_TSBMS001	FDC638APZ-TSBMS001
FDC638P_G	FDC638P-G
FDC638P_P	FDC638P-P
FDC638P_PG	FDC638P-PG
FDC638P_T	FDC638P-T
FDC638P_TG	FDC638P-TG
FDC6401N_T	FDC6401N-T
FDC6401N_X	FDC6401N-X
FDC640P_NBAD004A	FDC640P-NBAD004A
FDC640P_T	FDC640P-T
FDC6420C_T	FDC6420C-T
FDC642P_F085	FDC642P-F085
FDC642P_F085P	FDC642P-F085P
FDC642P_G	FDC642P-G
FDC642P_SB4N006P	FDC642P-SB4N006P
FDC642P_TSB4N006	FDC642P-TSB4N006
FDC645N_T	FDC645N-T
FDC6506P_NB4S006A	FDC6506P-NB4S006A
FDC654P_G	FDC654P-G
FDC654P_NBGT006	FDC654P-NBGT006
FDC654P_T	FDC654P-T
FDC654P_TG	FDC654P-TG
FDC655BN_F065	FDC655BN-F065
FDC655BN_F40	FDC655BN-F40
FDC655BN_G	FDC655BN-G
FDC655BN_NBNN007	FDC655BN-NBNN007
FDC6561AN_F169	FDC6561AN-F169
FDC6561AN_NB5S007A	FDC6561AN-NB5S007A
FDC658AP_G	FDC658AP-G
FDC658AP_SBAD011	FDC658AP-SBAD011
FDC658AP_T	FDC658AP-T
FDC658AP_TG	FDC658AP-TG
FDC658P_F169	FDC658P-F169
FDC658P_T	FDC658P-T
FDC8886_T	FDC8886-T
FDD10AN06A0_F085	FDD10AN06A0-F085
FDD120AN15A0_F085	FDD120AN15A0-F085
FDD120AN15A0_W82016B	FDD120AN15A0-W82016B
FDD13AN06A0_F085	FDD13AN06A0-F085
FDD14AN06LA0_F085	FDD14AN06LA0-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDD14AN06LA0_SB82165	FDD14AN06LA0-SB82165
FDD14AN06LA0_SB82248	FDD14AN06LA0-SB82248
FDD16AN08A0_F085	FDD16AN08A0-F085
FDD16AN08A0_SB82033A	FDD16AN08A0-SB82033A
FDD20AN06A0_F085	FDD20AN06A0-F085
FDD20AN06A0_SB82269	FDD20AN06A0-SB82269
FDD24AN06LA0_F085	FDD24AN06LA0-F085
FDD24AN06LA0_SB82249	FDD24AN06LA0-SB82249
FDD2572_F085	FDD2572-F085
FDD2572_SB82094	FDD2572-SB82094
FDD2670_F169	FDD2670-F169
FDD26AN06A0_F085	FDD26AN06A0-F085
FDD26AN06A0_SB82186	FDD26AN06A0-SB82186
FDD3510H_F169	FDD3510H-F169
FDD3670_F169	FDD3670-F169
FDD3672_F085	FDD3672-F085
FDD3680_F169	FDD3680-F169
FDD3682_F085	FDD3682-F085
FDD3682_NB82112	FDD3682-NB82112
FDD3690_F169	FDD3690-F169
FDD3860_G	FDD3860-G
FDD4141_F085	FDD4141-F085
FDD4141_F085P	FDD4141-F085P
FDD4141_TF085	FDD4141-TF085
FDD4243_F085	FDD4243-F085
FDD4243_F085P	FDD4243-F085P
FDD4243_G	FDD4243-G
FDD4243_TF085	FDD4243-TF085
FDD4685_F085	FDD4685-F085
FDD4685_F085P	FDD4685-F085P
FDD4685_SN00011	FDD4685-SN00011
FDD4685_SN00011P	FDD4685-SN00011P
FDD4685_T	FDD4685-T
FDD4685_TF085	FDD4685-TF085
FDD4685_TSN00011	FDD4685-TSN00011
FDD5612_F169	FDD5612-F169
FDD5614P_F169	FDD5614P-F169
FDD5670_F169	FDD5670-F169
FDD5680_F169	FDD5680-F169
FDD5690_F169	FDD5690-F169



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDD5810_F085	FDD5810-F085
FDD5810_SB82124	FDD5810-SB82124
FDD5N50FTM_TWS	FDD5N50FTM-TWS
FDD5N50FTM_WS	FDD5N50FTM-WS
FDD5N50TM_WS	FDD5N50TM-WS
FDD5N50UTM_WS	FDD5N50UTM-WS
FDD6530A_F169	FDD6530A-F169
FDD6630A_B5N004A	FDD6630A-B5N004A
FDD6630A_F169	FDD6630A-F169
FDD6637_F085	FDD6637-F085
FDD6637_SB82222	FDD6637-SB82222
FDD6637_SB82222P	FDD6637-SB82222P
FDD6637_T	FDD6637-T
FDD6637_TSB82222	FDD6637-TSB82222
FDD6685_G	FDD6685-G
FDD6685_T	FDD6685-T
FDD6685_TG	FDD6685-TG
FDD6N50TM_F085	FDD6N50TM-F085
FDD6N50TM_WS	FDD6N50TM-WS
FDD8424H_F085A	FDD8424H-F085A
FDD8424H_T	FDD8424H-T
FDD8444L_F085	FDD8444L-F085
FDD8444_F085	FDD8444-F085
FDD8444_F085P	FDD8444-F085P
FDD8444_TF085	FDD8444-TF085
FDD8445_F085	FDD8445-F085
FDD8445_F085P	FDD8445-F085P
FDD8445_TF085	FDD8445-TF085
FDD8447L_F085	FDD8447L-F085
FDD8453LZ_F085	FDD8453LZ-F085
FDD86367_F085	FDD86367-F085
FDD86369_F085	FDD86369-F085
FDD86380_F085	FDD86380-F085
FDD86381_F085	FDD86381-F085
FDD8647L_T	FDD8647L-T
FDD86567_F085	FDD86567-F085
FDD86569_F085	FDD86569-F085
FDD86580_F085	FDD86580-F085
FDD86581_F085	FDD86581-F085
FDD8870_F085	FDD8870-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDD8880_G	FDD8880-G
FDD8880_SN00319	FDD8880-SN00319
FDD8896 F085	FDD8896-F085
FDD8896_G	FDD8896-G
FDD8896_NBSW006	FDD8896-NBSW006
FDD8896_NBSW006P	FDD8896-NBSW006P
FDD8896_SN00320	FDD8896-SN00320
FDD8896_TNBSW006	FDD8896-TNBSW006
FDD9407L F085	FDD9407L-F085
FDD9407 F085	FDD9407-F085
FDD9409L F085	FDD9409L-F085
FDD9409 F085	FDD9409-F085
FDD9410L F085	FDD9410L-F085
FDD9410 F085	FDD9410-F085
FDD9411L F085	FDD9411L-F085
FDD9411 F085	FDD9411-F085
FDDS100H06 F085	FDDS100H06-F085
PDFMA2P029Z F106	PDFMA2P029Z-F106
PDFMA2P029Z T	PDFMA2P029Z-T
PDFMA2P029Z_TF106	PDFMA2P029Z-TF106
PDFMA3N109 T	PDFMA3N109-T
PDFMA3P029Z T	PDFMA3P029Z-T
PDFME3N311ZT T	PDFME3N311ZT-T
FDFS2P106A F169	FDFS2P106A-F169
FDFS2P106A T	FDFS2P106A-T
FDG312P F169	FDG312P-F169
FDG313N F169	FDG313N-F169
FDG313N T	FDG313N-T
FDG327NZ T	FDG327NZ-T
FDG328P T	FDG328P-T
FDG6301N F085	FDG6301N-F085
FDG6301N_F085P	FDG6301N-F085P
FDG6301N F169	FDG6301N-F169
FDG6301N_G	FDG6301N-G
FDG6301N_T	FDG6301N-T
FDG6301N_TG	FDG6301N-TG
FDG6303N F169	FDG6303N-F169
FDG6303N F169G	FDG6303N-F169G
FDG6303N T	FDG6303N-T
FDG6303N_X	FDG6303N-X



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDG6304P_F169	FDG6304P-F169
FDG6304P_T	FDG6304P-T
FDG6304P_X	FDG6304P-X
FDG6306P_T	FDG6306P-T
FDG6308P_T	FDG6308P-T
FDG6316P_T	FDG6316P-T
FDG6317NZ_T	FDG6317NZ-T
FDG6318PZ_T	FDG6318PZ-T
FDG6320C_F169	FDG6320C-F169
FDG6321C_F169	FDG6321C-F169
FDG6322C_F169	FDG6322C-F169
FDG6322C_T	FDG6322C-T
FDG6323L_F169	FDG6323L-F169
FDG6323L_T	FDG6323L-T
FDG6324L_F169	FDG6324L-F169
FDG6324L_Z	FDG6324L-Z
FDG6332C_F085	FDG6332C-F085
FDG6332C_F085P	FDG6332C-F085P
FDG6332C_G	FDG6332C-G
FDG6332C_PG	FDG6332C-PG
FDG6332C_T	FDG6332C-T
FDG6332C_TF085	FDG6332C-TF085
FDG6332C_TG	FDG6332C-TG
FDG6332C_Z	FDG6332C-Z
FDG6335N_T	FDG6335N-T
FDG6342L_F169	FDG6342L-F169
FDG6342L_Z	FDG6342L-Z
FDG8842CZ_F169	FDG8842CZ-F169
FDG8842CZ_T	FDG8842CZ-T
FDG8842CZ_Z	FDG8842CZ-Z
FDG8850NZ_T	FDG8850NZ-T
FDH055N15A_SN00358	FDH055N15A-SN00358
FDH45N50F_F133	FDH45N50F-F133
FDH50N50_F133	FDH50N50-F133
FDH5500_F085	FDH5500-F085
FDH5500_SB82257	FDH5500-SB82257
FDI045N10A_F102	FDI045N10A-F102
FDI9406_F085	FDI9406-F085
FDI9409_F085	FDI9409-F085
FDLL4148_D87Z	FDLL4148-D87Z



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDLL4448_D87Z	FDLL4448-D87Z
FDM3622_T	FDM3622-T
FDMA1023PZ_F106	FDMA1023PZ-F106
FDMA1023PZ_TF106	FDMA1023PZ-TF106
FDMA1024NZ_F130	FDMA1024NZ-F130
FDMA1024NZ_T	FDMA1024NZ-T
FDMA1028NZ_F021	FDMA1028NZ-F021
FDMA1028NZ_TF021	FDMA1028NZ-TF021
FDMA1032CZ_P	FDMA1032CZ-P
FDMA1032CZ_T	FDMA1032CZ-T
FDMA2002NZ_T	FDMA2002NZ-T
FDMA291P_T	FDMA291P-T
FDMA3027PZ_F130	FDMA3027PZ-F130
FDMA3028N_F130	FDMA3028N-F130
FDMA3028N_T	FDMA3028N-T
FDMA3028N_TF130	FDMA3028N-TF130
FDMA410NZ_T	FDMA410NZ-T
FDMA430NZ_T	FDMA430NZ-T
FDMA507PZ_T	FDMA507PZ-T
FDMA510PZ_P	FDMA510PZ-P
FDMA510PZ_T	FDMA510PZ-T
FDMA530PZ_T	FDMA530PZ-T
FDMA6023PZT_SN00198	FDMA6023PZT-SN00198
FDMA6023PZT_T	FDMA6023PZT-T
FDMA710PZ_P	FDMA710PZ-P
FDMA710PZ_T	FDMA710PZ-T
FDMA7632_T	FDMA7632-T
FDMA8878_F130	FDMA8878-F130
FDMA8878_T	FDMA8878-T
FDMA905P_F147	FDMA905P-F147
FDMA905P_SN00294	FDMA905P-SN00294
FDMA910PZ_T	FDMA910PZ-T
FDMB2308PZ_Z	FDMB2308PZ-Z
FDMB3800N_P	FDMB3800N-P
FDMB3800N_T	FDMB3800N-T
FDMC0202S_P	FDMC0202S-P
FDMC0202S_T	FDMC0202S-T
FDMC0223S_P	FDMC0223S-P
FDMC0223S_T	FDMC0223S-T
FDMC0225_P	FDMC0225-P



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDMC0225_T	FDMC0225-T
FDMC0310AS_F127	FDMC0310AS-F127
FDMC2514SDC_P	FDMC2514SDC-P
FDMC2514SDC_T	FDMC2514SDC-T
FDMC2523P_T	FDMC2523P-T
FDMC2610_T	FDMC2610-T
FDMC3020DC_P	FDMC3020DC-P
FDMC3020DC_T	FDMC3020DC-T
FDMC3612_F169	FDMC3612-F169
FDMC3612_T	FDMC3612-T
FDMC4435BZ_F126	FDMC4435BZ-F126
FDMC4435BZ_F127	FDMC4435BZ-F127
FDMC4435BZ_T	FDMC4435BZ-T
FDMC4436BZ_T	FDMC4436BZ-T
FDMC510P_F106	FDMC510P-F106
FDMC510P_SN00292	FDMC510P-SN00292
FDMC510P_T	FDMC510P-T
FDMC5614P_F169	FDMC5614P-F169
FDMC610P_T	FDMC610P-T
FDMC6675BZ_T	FDMC6675BZ-T
FDMC6676BZ_T	FDMC6676BZ-T
FDMC6676PZ_P	FDMC6676PZ-P
FDMC6676PZ_T	FDMC6676PZ-T
FDMC6679AZ_F125	FDMC6679AZ-F125
FDMC6679AZ_P	FDMC6679AZ-P
FDMC6679AZ_T	FDMC6679AZ-T
FDMC6683_T	FDMC6683-T
FDMC7200S_T	FDMC7200S-T
FDMC7200_T	FDMC7200-T
FDMC7572S_T	FDMC7572S-T
FDMC7660DC_T	FDMC7660DC-T
FDMC7660S_T	FDMC7660S-T
FDMC7660_P	FDMC7660-P
FDMC7660_T	FDMC7660-T
FDMC7672S_F126	FDMC7672S-F126
FDMC7672S_T	FDMC7672S-T
FDMC7672_T	FDMC7672-T
FDMC7692S_F126	FDMC7692S-F126
FDMC7692S_F127	FDMC7692S-F127
FDMC7692_SN00203	FDMC7692-SN00203



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDMC7692_T	FDMC7692-T
FDMC8200S_P	FDMC8200S-P
FDMC8200S_SN00246	FDMC8200S-SN00246
FDMC8200S_T	FDMC8200S-T
FDMC8200S_Z	FDMC8200S-Z
FDMC8200_T	FDMC8200-T
FDMC8298_T	FDMC8298-T
FDMC8321LDC_SN00368	FDMC8321LDC-SN00368
FDMC8321L_T	FDMC8321L-T
FDMC8554_T	FDMC8554-T
FDMC8588A_T	FDMC8588A-T
FDMC8588_T	FDMC8588-T
FDMC86102LZ_P	FDMC86102LZ-P
FDMC86102LZ_T	FDMC86102LZ-T
FDMC86106LZ_P	FDMC86106LZ-P
FDMC86106LZ_T	FDMC86106LZ-T
FDMC86160_SN00365	FDMC86160-SN00365
FDMC86261P_T	FDMC86261P-T
FDMC86340_SN00344	FDMC86340-SN00344
FDMC8651_SN00293	FDMC8651-SN00293
FDMC86520L_P	FDMC86520L-P
FDMC86520L_T	FDMC86520L-T
FDMC8854_T	FDMC8854-T
FDMC8878_T	FDMC8878-T
FDMC8884_F126	FDMC8884-F126
FDMC8884_T	FDMC8884-T
FDMC9430L_F085	FDMC9430L-F085
FDME1024NZT_T	FDME1024NZT-T
FDME820NZT_P	FDME820NZT-P
FDME820NZT_T	FDME820NZT-T
FDME910PZT_P	FDME910PZT-P
FDME910PZT_T	FDME910PZT-T
FDMF5821DC_T	FDMF5821DC-T
FDMF5822DC_Z	FDMF5822DC-Z
FDMF6707B_SN00244	FDMF6707B-SN00244
FDMF6808N_P	FDMF6808N-P
FDMF6808N_T	FDMF6808N-T
FDMF6820C_SN00295	FDMF6820C-SN00295
FDMF6821C_Z	FDMF6821C-Z
FDMF6823C_Z	FDMF6823C-Z



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FD MF6824B_S N00323	FD MF6824B-SN00323
FD MF6840C_F013	FD MF6840C-F013
FD MQ8203_F169	FD MQ8203-F169
FD MS0346_T	FD MS0346-T
FD MS0349_T	FD MS0349-T
FD MS0355S_T	FD MS0355S-T
FD MS039N08B_S N00355	FD MS039N08B-SN00355
FD MS3600AS_T	FD MS3600AS-T
FD MS3600S_T	FD MS3600S-T
FD MS3602AS_T	FD MS3602AS-T
FD MS3602S_P	FD MS3602S-P
FD MS3602S_T	FD MS3602S-T
FD MS3604S_T	FD MS3604S-T
FD MS3606AS_P	FD MS3606AS-P
FD MS3606AS_T	FD MS3606AS-T
FD MS36101L_F085	FD MS36101L-F085
FD MS3610S_T	FD MS3610S-T
FD MS3615S_T	FD MS3615S-T
FD MS3616S_T	FD MS3616S-T
FD MS3622S_T	FD MS3622S-T
FD MS3626S_T	FD MS3626S-T
FD MS3660S_T	FD MS3660S-T
FD MS3669S_S N00345	FD MS3669S-SN00345
FD MS5360L_F085	FD MS5360L-F085
FD MS5361L_F085	FD MS5361L-F085
FD MS5362L_F085	FD MS5362L-F085
FD MS6673BZ_T	FD MS6673BZ-T
FD MS6681Z_P	FD MS6681Z-P
FD MS6681Z_T	FD MS6681Z-T
FD MS7556S_T	FD MS7556S-T
FD MS7558S_T	FD MS7558S-T
FD MS7560S_T	FD MS7560S-T
FD MS7570S_T	FD MS7570S-T
FD MS7572S_T	FD MS7572S-T
FD MS7602S_T	FD MS7602S-T
FD MS7603S_P	FD MS7603S-P
FD MS7603S_T	FD MS7603S-T
FD MS7620S_F106	FD MS7620S-F106
FD MS7620S_T	FD MS7620S-T
FD MS7658AS_S N00232	FD MS7658AS-SN00232



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDMS7660AS_T	FDMS7660AS-T
FDMS7680_T	FDMS7680-T
FDMS7681_T	FDMS7681-T
FDMS7694_SN00251	FDMS7694-SN00251
FDMS8320L_SN00312	FDMS8320L-SN00312
FDMS8460_T	FDMS8460-T
FDMS8560S_T	FDMS8560S-T
FDMS86101_SN00155	FDMS86101-SN00155
FDMS86101_SN00235	FDMS86101-SN00235
FDMS86350_SN00361	FDMS86350-SN00361
FDMS86368_F085	FDMS86368-F085
FDMS86369_F085	FDMS86369-F085
FDMS86380_F085	FDMS86380-F085
FDMS86381_F085	FDMS86381-F085
FDMS86540_SN00379	FDMS86540-SN00379
FDMS86568_F085	FDMS86568-F085
FDMS86569_F085	FDMS86569-F085
FDMS86580_F085	FDMS86580-F085
FDMS86581_F085	FDMS86581-F085
FDMS8670S_T	FDMS8670S-T
FDMS9408L_F085	FDMS9408L-F085
FDMS9408_F085	FDMS9408-F085
FDMS9409L_F085	FDMS9409L-F085
FDMS9409_F085	FDMS9409-F085
FDMS9410L_F085	FDMS9410L-F085
FDMS9410_F085	FDMS9410-F085
FDMS9411L_F085	FDMS9411L-F085
FDMS9411_F085	FDMS9411-F085
FDMS9620S_T	FDMS9620S-T
FDN302P_G	FDN302P-G
FDN302P_T	FDN302P-T
FDN304PZ_T	FDN304PZ-T
FDN304P_T	FDN304P-T
FDN306P_T	FDN306P-T
FDN327N_G	FDN327N-G
FDN327N_T	FDN327N-T
FDN327N_TG	FDN327N-TG
FDN335N_F169	FDN335N-F169
FDN336P_F169	FDN336P-F169
FDN337N_F169	FDN337N-F169



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDN337N_G	FDN337N-G
FDN337N_PG	FDN337N-PG
FDN337N T	FDN337N-T
FDN337N TG	FDN337N-TG
FDN338P T	FDN338P-T
FDN339AN F169	FDN339AN-F169
FDN339AN T	FDN339AN-T
FDN340P G	FDN340P-G
FDN340P T	FDN340P-T
FDN340P TG	FDN340P-TG
FDN342P F169	FDN342P-F169
FDN342P T	FDN342P-T
FDN352AP T	FDN352AP-T
FDN357N F169	FDN357N-F169
FDN358P G	FDN358P-G
FDN358P T	FDN358P-T
FDN359AN F169	FDN359AN-F169
FDN359AN T	FDN359AN-T
FDN359BN TF095	FDN359BN-TF095
FDN360P G	FDN360P-G
FDN360P_NBGT003B	FDN360P-NBGT003B
FDN360P T	FDN360P-T
FDN5618P F169	FDN5618P-F169
FDN5618P SB4N007	FDN5618P-SB4N007
FDN5618P SB4N007P	FDN5618P-SB4N007P
FDN5618P T	FDN5618P-T
FDN5618P X	FDN5618P-X
FDN5630 F169	FDN5630-F169
FDN5630 G	FDN5630-G
FDN5632N F085	FDN5632N-F085
FDN86501LZ SN00389	FDN86501LZ-SN00389
FDP020N06B F102	FDP020N06B-F102
FDP020N06B SN00330	FDP020N06B-SN00330
FDP020N06B TSN00330	FDP020N06B-TSN00330
FDP023N08B F102	FDP023N08B-F102
FDP023N08B SN00325	FDP023N08B-SN00325
FDP027N08B F102	FDP027N08B-F102
FDP030N06B F102	FDP030N06B-F102
FDP032N08B F102	FDP032N08B-F102
FDP032N08 F102	FDP032N08-F102



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDP038AN06A0_F102	FDP038AN06A0-F102
FDP038AN06A0_SN00240	FDP038AN06A0-SN00240
FDP039N08B_F102	FDP039N08B-F102
FDP045N10A_F102	FDP045N10A-F102
FDP045N10A_TF102	FDP045N10A-TF102
FDP047AN08A0_F102	FDP047AN08A0-F102
FDP047AN08A0_G	FDP047AN08A0-G
FDP047N08V_F102	FDP047N08V-F102
FDP047N08_F102	FDP047N08-F102
FDP053N08B_F102	FDP053N08B-F102
FDP054N10_SN00215	FDP054N10-SN00215
FDP075N15A_F102	FDP075N15A-F102
FDP083N15A_F102	FDP083N15A-F102
FDP085N10A_F102	FDP085N10A-F102
FDP13AN06A0_SW82126	FDP13AN06A0-SW82126
FDP150N10A_F102	FDP150N10A-F102
FDP2710_F085	FDP2710-F085
FDP2710_SW82258	FDP2710-SW82258
FDP3682_SB82034	FDP3682-SB82034
FDP42AN15A0_SB82024A	FDP42AN15A0-SB82024A
FDP5500_F085	FDP5500-F085
FDP6030BL_F169	FDP6030BL-F169
FDP8442_F085	FDP8442-F085
FDP8443_F085	FDP8443-F085
FDP86363_F085	FDP86363-F085
FDP8870_F085	FDP8870-F085
FDP8874_SN00117	FDP8874-SN00117
FDPC1012S_P	FDPC1012S-P
FDPC4044_P	FDPC4044-P
FDPC8012S_T	FDPC8012S-T
FDPC8016S_T	FDPC8016S-T
FDPF035N06B_F152	FDPF035N06B-F152
FDPF18N20FT_G	FDPF18N20FT-G
FDPF18N50T_G	FDPF18N50T-G
FDPF7N50U_G	FDPF7N50U-G
FDS2670_F169	FDS2670-F169
FDS2670_T	FDS2670-T
FDS2672_F085	FDS2672-F085
FDS2672_TF085	FDS2672-TF085
FDS3512_F169	FDS3512-F169



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDS3580_F169	FDS3580-F169
FDS3890_F169	FDS3890-F169
FDS4141_F085	FDS4141-F085
FDS4141_SN00136	FDS4141-SN00136
FDS4141_SN00136P	FDS4141-SN00136P
FDS4141_T	FDS4141-T
FDS4435A_F169	FDS4435A-F169
FDS4435A_T	FDS4435A-T
FDS4435BZ_F085	FDS4435BZ-F085
FDS4435BZ_F171	FDS4435BZ-F171
FDS4435BZ_F171G	FDS4435BZ-F171G
FDS4435BZ_G	FDS4435BZ-G
FDS4435BZ_T	FDS4435BZ-T
FDS4435BZ_TG	FDS4435BZ-TG
FDS4465_F085	FDS4465-F085
FDS4465_G	FDS4465-G
FDS4465_PG	FDS4465-PG
FDS4465_SN00187	FDS4465-SN00187
FDS4465_SN00219	FDS4465-SN00219
FDS4465_T	FDS4465-T
FDS4465_TG	FDS4465-TG
FDS4480_SN00028	FDS4480-SN00028
FDS4488_F169	FDS4488-F169
FDS4559_F085	FDS4559-F085
FDS4559_F169	FDS4559-F169
FDS4559_TF085	FDS4559-TF085
FDS4675_BAA004AP	FDS4675-BAA004AP
FDS4675_F085	FDS4675-F085
FDS4675_SBAA004A	FDS4675-SBAA004A
FDS4675_T	FDS4675-T
FDS4675_TBAA004A	FDS4675-TBAA004A
FDS4685_NF074	FDS4685-NF074
FDS4685_T	FDS4685-T
FDS4897AC_Z	FDS4897AC-Z
FDS4897C_T	FDS4897C-T
FDS4935BZ_SBME002	FDS4935BZ-SBME002
FDS4935BZ_T	FDS4935BZ-T
FDS4935BZ_ZSBME002	FDS4935BZ-ZSBME002
FDS5670_F169	FDS5670-F169
FDS5670_T	FDS5670-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDS5690_F169	FDS5690-F169
FDS5690_NBBM009A	FDS5690-NBBM009A
FDS6294_T	FDS6294-T
FDS6298_G	FDS6298-G
FDS6375_T	FDS6375-T
FDS6570A_F169	FDS6570A-F169
FDS6574A_T	FDS6574A-T
FDS6575_T	FDS6575-T
FDS6576_T	FDS6576-T
FDS6612A_NB5E029A	FDS6612A-NB5E029A
FDS6673BZ_F085	FDS6673BZ-F085
FDS6673BZ_F171	FDS6673BZ-F171
FDS6673BZ_G	FDS6673BZ-G
FDS6675BZ_F171	FDS6675BZ-F171
FDS6675BZ_G	FDS6675BZ-G
FDS6675BZ_T	FDS6675BZ-T
FDS6675_F169	FDS6675-F169
FDS6676AS_G	FDS6676AS-G
FDS6676AS_T	FDS6676AS-T
FDS6679AZ_F171	FDS6679AZ-F171
FDS6679AZ_G	FDS6679AZ-G
FDS6679AZ_T	FDS6679AZ-T
FDS6680A_NBBI005A	FDS6680A-NBBI005A
FDS6680A_TBBI005A	FDS6680A-TBBI005A
FDS6681Z_G	FDS6681Z-G
FDS6681Z_P	FDS6681Z-P
FDS6681Z_PG	FDS6681Z-PG
FDS6685_NBCM003A	FDS6685-NBCM003A
FDS6685_TBCM003A	FDS6685-TBCM003A
FDS6690AS_G	FDS6690AS-G
FDS6690AS_NBNU001	FDS6690AS-NBNU001
FDS6690A_GNB23008	FDS6690A-GNB23008
FDS6690A_NBNP006	FDS6690A-NBNP006
FDS6699S_T	FDS6699S-T
FDS6875_F169	FDS6875-F169
FDS6890A_F169	FDS6890A-F169
FDS6890A_T	FDS6890A-T
FDS6898AZ_F085	FDS6898AZ-F085
FDS6898AZ_SBDP002	FDS6898AZ-SBDP002
FDS6898AZ_T	FDS6898AZ-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDS6898A_G	FDS6898A-G
FDS6900AS_G	FDS6900AS-G
FDS6900AS_ZG	FDS6900AS-ZG
FDS6910_T	FDS6910-T
FDS6910_Z	FDS6910-Z
FDS6912A_F095	FDS6912A-F095
FDS6930A_F169	FDS6930A-F169
FDS6930A_T	FDS6930A-T
FDS6961A_F169	FDS6961A-F169
FDS6975_F169	FDS6975-F169
FDS6975_SBAM003P	FDS6975-SBAM003P
FDS6975_T	FDS6975-T
FDS6975_TSBAM003	FDS6975-TSBAM003
FDS6982AS_F095	FDS6982AS-F095
FDS6982AS_G	FDS6982AS-G
FDS6982AS_T	FDS6982AS-T
FDS6984AS_Z	FDS6984AS-Z
FDS6986AS_F095	FDS6986AS-F095
FDS6986AS_SN00192	FDS6986AS-SN00192
FDS6986AS_T	FDS6986AS-T
FDS6986AS_Z	FDS6986AS-Z
FDS6990A_T	FDS6990A-T
FDS8433A_F169	FDS8433A-F169
FDS8433A_F169G	FDS8433A-F169G
FDS8433A_G	FDS8433A-G
FDS8433A_T	FDS8433A-T
FDS8433A_TG	FDS8433A-TG
FDS8449_F085	FDS8449-F085
FDS8449_F085P	FDS8449-F085P
FDS8449_G	FDS8449-G
FDS8449_SN00242	FDS8449-SN00242
FDS8449_T	FDS8449-T
FDS8449_TG	FDS8449-TG
FDS86140_T	FDS86140-T
FDS8672S_T	FDS8672S-T
FDS8817NZ_G	FDS8817NZ-G
FDS8817NZ_SBSP001	FDS8817NZ-SBSP001
FDS8858CZ_T	FDS8858CZ-T
FDS8858CZ_Z	FDS8858CZ-Z
FDS8876_F40	FDS8876-F40



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDS8878_F123	FDS8878-F123
FDS8878_G	FDS8878-G
FDS8880_G	FDS8880-G
FDS8880_SN00134	FDS8880-SN00134
FDS8884_G	FDS8884-G
FDS8896_SBSW008	FDS8896-SBSW008
FDS89141_T	FDS89141-T
FDS89161LZ_T	FDS89161LZ-T
FDS8935_F169	FDS8935-F169
FDS8949_F085	FDS8949-F085
FDS8949_SN00247	FDS8949-SN00247
FDS8949_T	FDS8949-T
FDS8949_XSN00247	FDS8949-XSN00247
FDS8958A_F085	FDS8958A-F085
FDS8958B_G	FDS8958B-G
FDS8960C_Z	FDS8960C-Z
FDS8978_F40	FDS8978-F40
FDS8984_F085	FDS8984-F085
FDS8984_F40	FDS8984-F40
FDS9431A_F085	FDS9431A-F085
FDS9431A_F169	FDS9431A-F169
FDS9431A_T	FDS9431A-T
FDS9431A_TF085	FDS9431A-TF085
FDS9435A_NBAD008	FDS9435A-NBAD008
FDS9435A_T	FDS9435A-T
FDS9933A_T	FDS9933A-T
FDS9958_F085	FDS9958-F085
FDS9958_SB82210	FDS9958-SB82210
FDS9958_SB82210P	FDS9958-SB82210P
FDSS2407_SB82086	FDSS2407-SB82086
FDSS2407_SB82086P	FDSS2407-SB82086P
FDSS2407_SB82097	FDSS2407-SB82097
FDSS2407_SB82097P	FDSS2407-SB82097P
FDSS2407_TSB82097	FDSS2407-TSB82097
FDT3612_F169	FDT3612-F169
FDT3612_SB82273	FDT3612-SB82273
FDT3612_SN00151	FDT3612-SN00151
FDT3612_TSN00151	FDT3612-TSN00151
FDT434P_F169	FDT434P-F169
FDT439N_F169	FDT439N-F169



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDT457N_F169	FDT457N-F169
FDT86113LZ_T	FDT86113LZ-T
FDV301N_F080	FDV301N-F080
FDV301N_F169	FDV301N-F169
FDV301N_F169G	FDV301N-F169G
FDV301N_G	FDV301N-G
FDV301N_NB9V003	FDV301N-NB9V003
FDV301N_NB9V005	FDV301N-NB9V005
FDV301N_NB9V008	FDV301N-NB9V008
FDV301N_NB9V008P	FDV301N-NB9V008P
FDV301N_T	FDV301N-T
FDV301N_TG	FDV301N-TG
FDV301N_TNB9V008	FDV301N-TNB9V008
FDV301N_X	FDV301N-X
FDV302P_F169	FDV302P-F169
FDV302P_NB8V001	FDV302P-NB8V001
FDV302P_T	FDV302P-T
FDV303N_F080	FDV303N-F080
FDV303N_F169	FDV303N-F169
FDV304P_D87Z	FDV304P-D87Z
FDV304P_F169	FDV304P-F169
FDV304P_T	FDV304P-T
FDV304P_X	FDV304P-X
FDV305N_T	FDV305N-T
FDWS5360L_F085	FDWS5360L-F085
FDWS86368_F085	FDWS86368-F085
FDWS86369_F085	FDWS86369-F085
FDWS86380_F085	FDWS86380-F085
FDWS9408_F085	FDWS9408-F085
FDWS9420_F085	FDWS9420-F085
FDY1002PZ_G	FDY1002PZ-G
FDY100PZ_G	FDY100PZ-G
FDY101PZ_T	FDY101PZ-T
FDY2000PZ_T	FDY2000PZ-T
FDY3000NZ_T	FDY3000NZ-T
FDY4000CZ_Z	FDY4000CZ-Z
FDZ1827NZ_P	FDZ1827NZ-P
FDZ1827NZ_T	FDZ1827NZ-T
FDZ1905PZ_T	FDZ1905PZ-T
FDZ191P_T	FDZ191P-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FDZ375P_T	FDZ375P-T
FDZ451PZ_P	FDZ451PZ-P
FFB20UP20DN F085	FFB20UP20DN-F085
FFB20UP20DN_SB82195	FFB20UP20DN-SB82195
FFB20UP20DN_SB82195P	FFB20UP20DN-SB82195P
FFB20UP20DN_SB82216	FFB20UP20DN-SB82216
FFB2227A_SN00289	FFB2227A-SN00289
FFB3904_NB23296	FFB3904-NB23296
FFB5551_SBDB002A	FFB5551-SBDB002A
FFD08S60S_F085	FFD08S60S-F085
FFH50US60S_F085	FFH50US60S-F085
FFH50US60S_T	FFH50US60S-T
FFPF20UP60DNTU G	FFPF20UP60DNTU-G
FFSH15120ADN F155	FFSH15120ADN-F155
FFSH20120ADN F155	FFSH20120ADN-F155
FFSH30120ADN F155	FFSH30120ADN-F155
FFSH40120ADN F155	FFSH40120ADN-F155
FGA15N120ANTDTU F109	FGA15N120ANTDTU-F109
FGA20S125P_SN00336	FGA20S125P-SN00336
FGA25N120ANTDTU F109	FGA25N120ANTDTU-F109
FGA25S125P_SN00337	FGA25S125P-SN00337
FGB20N60SFD F085	FGB20N60SFD-F085
FGB3040CS_SB82142	FGB3040CS-SB82142
FGB3040G2 F085	FGB3040G2-F085
FGB3056 F085	FGB3056-F085
FGB3236 F085	FGB3236-F085
FGB3245G2 F085	FGB3245G2-F085
FGB3440G2 F085	FGB3440G2-F085
FGB40T65SPD F085	FGB40T65SPD-F085
FGBS3040E1 F085	FGBS3040E1-F085
FGBS3040E1_SN00193	FGBS3040E1-SN00193
FGBS3040E1_SN00390	FGBS3040E1-SN00390
FGBS3040E1_SN00392	FGBS3040E1-SN00392
FGD2736G3 F085	FGD2736G3-F085
FGD3040G2 F065	FGD3040G2-F065
FGD3040G2 F085	FGD3040G2-F085
FGD3040G2_SN00296	FGD3040G2-SN00296
FGD3040G2_SN00334	FGD3040G2-SN00334
FGD3040G2_SN00353	FGD3040G2-SN00353
FGD3245G2 F085	FGD3245G2-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FGD3325G2_F085	FGD3325G2-F085
FGD3440G2_F085	FGD3440G2-F085
FGD3N60LSDTM_SB82154	FGD3N60LSDTM-SB82154
FGD3N60LSDTM_T	FGD3N60LSDTM-T
FGD4536TM_SN00306	FGD4536TM-SN00306
FGH12040WD_F155	FGH12040WD-F155
FGH15T120SMD_F155	FGH15T120SMD-F155
FGH20N60SFDTU_F085	FGH20N60SFDTU-F085
FGH25T120SMD_F155	FGH25T120SMD-F155
FGH30T65UPDT_F155	FGH30T65UPDT-F155
FGH40N60SFDTU_F085	FGH40N60SFDTU-F085
FGH40N60SMD_F085	FGH40N60SMD-F085
FGH40N60SMD_F085	FGH40N60SMD-F085
FGH40N60UFTU_SN00007	FGH40N60UFTU-SN00007
FGH40N65UFDTU_F085	FGH40N65UFDTU-F085
FGH40T100SMD_F155	FGH40T100SMD-F155
FGH40T120SMD_F155	FGH40T120SMD-F155
FGH40T120SMD_SN00363	FGH40T120SMD-SN00363
FGH40T120SMD_SN00388	FGH40T120SMD-SN00388
FGH40T65SHDF_F155	FGH40T65SHDF-F155
FGH40T65SHD_F155	FGH40T65SHD-F155
FGH40T65SH_F155	FGH40T65SH-F155
FGH40T65SPD_F085	FGH40T65SPD-F085
FGH40T65SPD_F155	FGH40T65SPD-F155
FGH40T65UQDF_F155	FGH40T65UQDF-F155
FGH40T70SHD_F155	FGH40T70SHD-F155
FGH50T65SQD_F155	FGH50T65SQD-F155
FGH60N60SFDTU_F085	FGH60N60SFDTU-F085
FGH60N60SMD_F085	FGH60N60SMD-F085
FGH60N60UFDTU_F085	FGH60N60UFDTU-F085
FGH60T65SHD_F155	FGH60T65SHD-F155
FGH75T65SHDT_F155	FGH75T65SHDT-F155
FGH75T65SHD_F155	FGH75T65SHD-F155
FGH75T65SQD_F155	FGH75T65SQD-F155
FGH75T65UPD_F085	FGH75T65UPD-F085
FGH75T65UPD_F155	FGH75T65UPD-F155
FGH75T65UPD_T	FGH75T65UPD-T
FGI3040G2_F085	FGI3040G2-F085
FGI3236_F085	FGI3236-F085
FGP3040G2_F085	FGP3040G2-F085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FGP3440G2_F085	FGP3440G2-F085
FGY120T65SPD_F085	FGY120T65SPD-F085
FGY160T65SPD_F085	FGY160T65SPD-F085
FIN1031MTCX_T	FIN1031MTCX-T
FIN1047MX_T	FIN1047MX-T
FJP13007H1TU_F080	FJP13007H1TU-F080
FJP13007H1TU_F129	FJP13007H1TU-F129
FJP13007H2TU_F080	FJP13007H2TU-F080
FL7730MY_F116	FL7730MY-F116
FL7732M_F116	FL7732M-F116
FL7930BMX_F172G	FL7930BMX-F172G
FL7930BMX_G	FL7930BMX-G
FL7930CMX_F172G	FL7930CMX-F172G
FL7930CMX_G	FL7930CMX-G
FMBM5401_SB74001	FMBM5401-SB74001
FMBM5551_SB16001	FMBM5551-SB16001
FMS6141S5X_SN00241	FMS6141S5X-SN00241
FMS6143CSX_NS5C002	FMS6143CSX-NS5C002
FMS6143CSX_XNS5C002	FMS6143CSX-XNS5C002
FMS6346MTC20X_T	FMS6346MTC20X-T
FMS6353EUCX_T	FMS6353EUCX-T
FMS6364AMTC14X_T	FMS6364AMTC14X-T
FMS6502MTC24X_T	FMS6502MTC24X-T
FMS6502MTC24X_X	FMS6502MTC24X-X
FMS7000MTC14X_T	FMS7000MTC14X-T
FNA23512A_T	FNA23512A-T
FNB40560_SN00282	FNB40560-SN00282
FNB50560T1_T	FNB50560T1-T
FOD817X_5700W	FOD817X-5700W
FOD817X_5701W	FOD817X-5701W
FODM3012R2V_NF098	FODM3012R2V-NF098
FODM3012R2_NF098	FODM3012R2-NF098
FODM3012_NF098	FODM3012-NF098
FODM3022R2V_NF098	FODM3022R2V-NF098
FODM3022R2_NF098	FODM3022R2-NF098
FODM3022_NF098	FODM3022-NF098
FODM3023R2_NF098	FODM3023R2-NF098
FODM3023R4_NF098	FODM3023R4-NF098
FODM3023_NF098	FODM3023-NF098
FODM3052R2_NF098	FODM3052R2-NF098



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FODM3052_NF098	FODM3052-NF098
FODM3053R2V_NF098	FODM3053R2V-NF098
FODM3053R2_NF098	FODM3053R2-NF098
FODM3053V_NF098	FODM3053V-NF098
FODM3053_NF098	FODM3053-NF098
FODM8801AR2_SN00324	FODM8801AR2-SN00324
FODM8801A_SN00324	FODM8801A-SN00324
FPDB40PH60B_SN00372	FPDB40PH60B-SN00372
FPDB50PH60_F166	FPDB50PH60-F166
FPDB60PH60B_SN00373	FPDB60PH60B-SN00373
FPDB60PH60B_SN00395	FPDB60PH60B-SN00395
FPF1005_SN00243	FPF1005-SN00243
FPF1009R_P	FPF1009R-P
FPF1009R_T	FPF1009R-T
FPF1038UCX_T	FPF1038UCX-T
FPF1039UCX_T	FPF1039UCX-T
FPF12045UCX_T	FPF12045UCX-T
FPF1204UCX_F013	FPF1204UCX-F013
FPF1320UCX_P	FPF1320UCX-P
FPF1320UCX_T	FPF1320UCX-T
FPF1504BUCX_T	FPF1504BUCX-T
FPF1C2P5MF07AM_T	FPF1C2P5MF07AM-T
FPF2193_T	FPF2193-T
FPF2195UCX_SN00331	FPF2195UCX-SN00331
FPF2195_SN00194	FPF2195-SN00194
FPF2195_TSN00194	FPF2195-TSN00194
FPF2280BUCX_F130	FPF2280BUCX-F130
FPF2280BUCX_F163	FPF2280BUCX-F163
FPF2280BUCX_PF130	FPF2280BUCX-PF130
FPF2280BUCX_TF130	FPF2280BUCX-TF130
FPF2281BUCX_F130	FPF2281BUCX-F130
FPF2290BUCX_F130	FPF2290BUCX-F130
FPF2411BUCX_F130	FPF2411BUCX-F130
FPF2495UCX_P	FPF2495UCX-P
FPF2495UCX_SN00309	FPF2495UCX-SN00309
FPF2495UCX_T	FPF2495UCX-T
FPF2496UCX_P	FPF2496UCX-P
FPF3688UCX_SN00396	FPF3688UCX-SN00396
FQA10N80C_F109	FQA10N80C-F109
FQA11N90C_F109	FQA11N90C-F109



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FQA11N90_F109	FQA11N90-F109
FQA13N50CF_T	FQA13N50CF-T
FQA13N50C_F109	FQA13N50C-F109
FQA13N80_F109	FQA13N80-F109
FQA16N50_F109	FQA16N50-F109
FQA24N60_T	FQA24N60-T
FQA6N90C_F109	FQA6N90C-F109
FQA7N80C_F109	FQA7N80C-F109
FQA8N90C_F109	FQA8N90C-F109
FQA90N15_F109	FQA90N15-F109
FQA9N90C_F109	FQA9N90C-F109
FQA9N90_F109	FQA9N90-F109
FQB10N50CFTM_WS	FQB10N50CFTM-WS
FQB11P06TM_SP001	FQB11P06TM-SP001
FQB11P06TM_SP001P	FQB11P06TM-SP001P
FQB11P06TM_TSP001	FQB11P06TM-TSP001
FQB12P20TM_SB82075	FQB12P20TM-SB82075
FQB12P20TM_SB82075P	FQB12P20TM-SB82075P
FQB12P20TM_TSB82075	FQB12P20TM-TSB82075
FQB19N20TM_T	FQB19N20TM-T
FQB22P10TM_F085	FQB22P10TM-F085
FQB22P10TM_T	FQB22P10TM-T
FQB25N33TM_F085	FQB25N33TM-F085
FQB25N33TM_NB82122	FQB25N33TM-NB82122
FQB25N33TM_NB82122P	FQB25N33TM-NB82122P
FQB27N25TM_F085	FQB27N25TM-F085
FQB27N25TM_F085P	FQB27N25TM-F085P
FQB27N25TM_TF085	FQB27N25TM-TF085
FQB33N10TM_T	FQB33N10TM-T
FQB34N20TM_AM002	FQB34N20TM-AM002
FQB34P10TM_F085	FQB34P10TM-F085
FQB34P10TM_F085P	FQB34P10TM-F085P
FQB34P10TM_TF085	FQB34P10TM-TF085
FQB47P06TM_AM002	FQB47P06TM-AM002
FQB5N60CTM_WS	FQB5N60CTM-WS
FQB5N90TM_SN00260	FQB5N90TM-SN00260
FQB7N60TM_WS	FQB7N60TM-WS
FQB7P20TM_F085	FQB7P20TM-F085
FQB7P20TM_F085P	FQB7P20TM-F085P
FQB8N60CTM_WS	FQB8N60CTM-WS



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FQD11P06TM_T	FQD11P06TM-T
FQD12N20LTM_F085	FQD12N20LTM-F085
FQD12N20LTM_F085P	FQD12N20LTM-F085P
FQD12N20LTM_T	FQD12N20LTM-T
FQD12N20LTM_TF085	FQD12N20LTM-TF085
FQD12P10TF_NB82105	FQD12P10TF-NB82105
FQD12P10TM_AS004	FQD12P10TM-AS004
FQD12P10TM_AS004P	FQD12P10TM-AS004P
FQD12P10TM_F085	FQD12P10TM-F085
FQD12P10TM_TAS004	FQD12P10TM-TAS004
FQD12P10TM_TF085	FQD12P10TM-TF085
FQD18N20V2TM_T	FQD18N20V2TM-T
FQD19N10LTM_T	FQD19N10LTM-T
FQD2N100TM_F101	FQD2N100TM-F101
FQD2N60CTM_SN00216	FQD2N60CTM-SN00216
FQD2N60CTM_WS	FQD2N60CTM-WS
FQD2N90TM_T	FQD2N90TM-T
FQD3N60CTM_WS	FQD3N60CTM-WS
FQD3P50TM_AM002BLT	FQD3P50TM-AM002BLT
FQD3P50TM_F085	FQD3P50TM-F085
FQD3P50TM_T	FQD3P50TM-T
FQD4N20TM_T	FQD4N20TM-T
FQD4N25TM_WS	FQD4N25TM-WS
FQD4P25TM_TWS	FQD4P25TM-TWS
FQD4P25TM_WS	FQD4P25TM-WS
FQD4P40TM_AM002	FQD4P40TM-AM002
FQD5N50CTM_WS	FQD5N50CTM-WS
FQD5N60CTM_WS	FQD5N60CTM-WS
FQD5P10TM_T	FQD5P10TM-T
FQD5P10TM_X	FQD5P10TM-X
FQD6N40CTM_NBEA002	FQD6N40CTM-NBEA002
FQD6N60CTM_WS	FQD6N60CTM-WS
FQD8P10TM_F085	FQD8P10TM-F085
FQD8P10TM_T	FQD8P10TM-T
FQD9N25TM_F080	FQD9N25TM-F080
FQD9N25TM_F085	FQD9N25TM-F085
FQD9N25TM_SBEK002	FQD9N25TM-SBEK002
FQD9N25TM_SBEK002P	FQD9N25TM-SBEK002P
FQD9N25TM_TF085	FQD9N25TM-TF085
FQH44N10_F133	FQH44N10-F133



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FQI27N25TU_F085	FQI27N25TU-F085
FQI27N25TU_SB82240	FQI27N25TU-SB82240
FQI27N25TU_TSB82240	FQI27N25TU-TSB82240
FQN1N60CTA_G	FQN1N60CTA-G
FQP11N40C_F105	FQP11N40C-F105
FQP11N40C_TF105	FQP11N40C-TF105
FQP13N50C_G	FQP13N50C-G
FQP16N25C_F105	FQP16N25C-F105
FQP19N20_T	FQP19N20-T
FQP27P06_SW82127	FQP27P06-SW82127
FQP27P06_T	FQP27P06-T
FQP2N40_F080	FQP2N40-F080
FQP2P40_F080	FQP2P40-F080
FQP3N50C_F080	FQP3N50C-F080
FQP4P40_T	FQP4P40-T
FQP50N06L_EPKE0003	FQP50N06L-EPKE0003
FQP50N06_T	FQP50N06-T
FQP6N70_T	FQP6N70-T
FQPF11N50CF_T	FQPF11N50CF-T
FQPF13N50C_T	FQPF13N50C-T
FQPF30N06L_T	FQPF30N06L-T
FQPF33N10_T	FQPF33N10-T
FQPF5N50CYDTU_T	FQPF5N50CYDTU-T
FQPF7N65CYDTU_T	FQPF7N65CYDTU-T
FQPF8N90C_T	FQPF8N90C-T
FQPF9N50CF_T	FQPF9N50CF-T
FQPF9P25_T	FQPF9P25-T
FQT1N60CTF_WS	FQT1N60CTF-WS
FQT1N80TF_WS	FQT1N80TF-WS
FQT3P20TF_SB82100	FQT3P20TF-SB82100
FQT3P20TF_TSB82100	FQT3P20TF-TSB82100
FQU12N20TU_T	FQU12N20TU-T
FQU13N06LTU_T	FQU13N06LTU-T
FQU13N06LTU_WS	FQU13N06LTU-WS
FQU2N50BTU_WS	FQU2N50BTU-WS
FQU2N60CTU_SN00217	FQU2N60CTU-SN00217
FQU2N90TU_AM002	FQU2N90TU-AM002
FQU2N90TU_WS	FQU2N90TU-WS
FQU4N50TU_WS	FQU4N50TU-WS
FQU5N50CTU_WS	FQU5N50CTU-WS



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FR011L5J_Z	FR011L5J-Z
FR014H5JZ_T	FR014H5JZ-T
FSA1208BQX_P	FSA1208BQX-P
FSA1208BQX_T	FSA1208BQX-T
FSA2259UMX_F106	FSA2259UMX-F106
FSA2268L10X_F106	FSA2268L10X-F106
FSA2269UCX_T	FSA2269UCX-T
FSA2270TUMX_F106	FSA2270TUMX-F106
FSA2457UMX_T	FSA2457UMX-T
FSA2466UMX_F106	FSA2466UMX-F106
FSA2567UMX_F135	FSA2567UMX-F135
FSA266L8X_T	FSA266L8X-T
FSA3000L10X_F131	FSA3000L10X-F131
FSA3051TMX_F147	FSA3051TMX-F147
FSA3157P6X_G	FSA3157P6X-G
FSA3200UMX_F106	FSA3200UMX-F106
FSA6157L6X_T	FSA6157L6X-T
FSA642UMX_F106	FSA642UMX-F106
FSA644UCX_T	FSA644UCX-T
FSA8038UMSX_F106	FSA8038UMSX-F106
FSA8039AUMSX_F106	FSA8039AUMSX-F106
FSA8039AUMSX_TF106	FSA8039AUMSX-TF106
FSA8039UMSX_TF106	FSA8039UMSX-TF106
FSA8048UMX_F106	FSA8048UMX-F106
FSA8048UMX_TF106	FSA8048UMX-TF106
FSA831AL10X_F131	FSA831AL10X-F131
FSA831L10X_F131	FSA831L10X-F131
FSA839UCX_SB82278	FSA839UCX-SB82278
FSA9285UCX_T	FSA9285UCX-T
FSA9590UCX_T	FSA9590UCX-T
FSB117HNY_F116	FSB117HNY-F116
FSB50450AS_SN00272	FSB50450AS-SN00272
FSB560A_SN00165	FSB560A-SN00165
FSBB15CH60F_F166	FSBB15CH60F-F166
FSBB20CH60C_F172	FSBB20CH60C-F172
FSBB20CH60C_SN00374	FSBB20CH60C-SN00374
FSBB20CH60F_F166	FSBB20CH60F-F166
FSBB30CH60C_F172	FSBB30CH60C-F172
FSBB30CH60C_SN00375	FSBB30CH60C-SN00375
FSBB30CH60F_F166	FSBB30CH60F-F166



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FSBH0170NY_F116	FSBH0170NY-F116
FSBH0270NY_F116	FSBH0270NY-F116
FSBH0370NY_F116	FSBH0370NY-F116
FSBH0F70ANY_F116	FSBH0F70ANY-F116
FSBS15CH60F_F166	FSBS15CH60F-F166
FSD106LG_T	FSD106LG-T
FSD156MRBN_T	FSD156MRBN-T
FSDH321_T	FSDH321-T
FSDL0165RN_SN00228	FSDL0165RN-SN00228
FSDM0265RNB_T	FSDM0265RNB-T
FSDM0465REWDTU_T	FSDM0465REWDTU-T
FSDM0565REWDTU_T	FSDM0565REWDTU-T
FSDM07652REWDTU_T	FSDM07652REWDTU-T
FSEZ1317AMY_F116	FSEZ1317AMY-F116
FSFM300N_T	FSFM300N-T
FSGM300N_T	FSGM300N-T
FSL106HR_T	FSL106HR-T
FSL117MRIN_T	FSL117MRIN-T
FSL137MRIN_T	FSL137MRIN-T
FSL156MRISN_T	FSL156MRISN-T
FSQ0265RN_T	FSQ0265RN-T
FSQ0270RNA_SN00229	FSQ0270RNA-SN00229
FSQ0565RSWDTU_T	FSQ0565RSWDTU-T
FSSD06BQX_T	FSSD06BQX-T
FST16210MTDX_SB82221	FST16210MTDX-SB82221
FSUSB104UMX_T	FSUSB104UMX-T
FSUSB31L8X_T	FSUSB31L8X-T
FSUSB42UMX_F106	FSUSB42UMX-F106
FSUSB43L10X_F131	FSUSB43L10X-F131
FSUSB63UMX_F106	FSUSB63UMX-F106
FT7521L6X_F106	FT7521L6X-F106
FT8010MPX_F106	FT8010MPX-F106
FUSB301ATMX_SN00362	FUSB301ATMX-SN00362
FXLA0104QFX_F106	FXLA0104QFX-F106
FXLA102L8X_F106	FXLA102L8X-F106
FXLA104UM12X_F106	FXLA104UM12X-F106
FXLA104UMX_F106	FXLA104UMX-F106
FXLA104UMX_TF106	FXLA104UMX-TF106
FXMA2102L8X_F106	FXMA2102L8X-F106
FXMA2102L8X_T	FXMA2102L8X-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
FXMA2102UMX_F106	FXMA2102UMX-F106
FXMAR2102UMX_F106	FXMAR2102UMX-F106
FYV0704SMTF_T	FYV0704SMTF-T
G785_BSS123	G785-BSS123
H11AD9X_5660	H11AD9X-5660
H11AXM_5164	H11AXM-5164
H11AXM_5164SR2V	H11AXM-5164SR2V
H11LXM_5555R2	H11LXM-5555R2
H11SBDXM_108R2	H11SBDXM-108R2
H11ZXM_9107	H11ZXM-9107
HGTP12N60A4D_NW82098	HGTP12N60A4D-NW82098
HGTP12N60A4D_NW82098P	HGTP12N60A4D-NW82098P
HGTP12N60A4D_TNW82098	HGTP12N60A4D-TNW82098
HGTP7N60A4_F102	HGTP7N60A4-F102
HMA121CR3V_NF098	HMA121CR3V-NF098
HUF75329D3ST_R4820	HUF75329D3ST-R4820
HUF75545S3ST_F101	HUF75545S3ST-F101
HUF75545S3ST_SN00258	HUF75545S3ST-SN00258
HUF75639P3_F102	HUF75639P3-F102
HUF75639S3ST_S2515	HUF75639S3ST-S2515
HUF75645P3_SB82282	HUF75645P3-SB82282
HUF75645S3ST_F101	HUF75645S3ST-F101
HUF76139P3_NS2552	HUF76139P3-NS2552
HUF76409D3ST_S2457	HUF76409D3ST-S2457
HUF76409D3ST_SB82270	HUF76409D3ST-SB82270
HUF76419S3ST_F085	HUF76419S3ST-F085
HUF76419S3ST_R4908	HUF76419S3ST-R4908
HUF76629D3ST_F085	HUF76629D3ST-F085
HUF76629D3ST_SB82250	HUF76629D3ST-SB82250
HUF76633P3_F085	HUF76633P3-F085
HUF76633P3_R4883	HUF76633P3-R4883
HUF76633S3ST_F085	HUF76633S3ST-F085
HUF76633S3ST_SB82274	HUF76633S3ST-SB82274
HUF76639S3ST_F085	HUF76639S3ST-F085
HUF76639S3ST_SB82251	HUF76639S3ST-SB82251
HUFA75344P3_SB82066	HUFA75344P3-SB82066
HUFA75639S3ST_F085A	HUFA75639S3ST-F085A
HUFA75639S3ST_S2457	HUFA75639S3ST-S2457
HUFA75852G3_F085	HUFA75852G3-F085
HUFA75852G3_SB82025A	HUFA75852G3-SB82025A



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
HUFA76407DK8T_F085	HUFA76407DK8T-F085
HUFA76407DK8T_F085P	HUFA76407DK8T-F085P
HUFA76407DK8T_TF085	HUFA76407DK8T-TF085
HUFA76407P3_SB82130	HUFA76407P3-SB82130
HUFA76409D3ST_B76008A	HUFA76409D3ST-B76008A
HUFA76409D3ST_R4974	HUFA76409D3ST-R4974
HUFA76413DK8T_B76001A	HUFA76413DK8T-B76001A
HUFA76413DK8T_F085	HUFA76413DK8T-F085
HUFA76413DK8T_F085P	HUFA76413DK8T-F085P
HUFA76413DK8T_TF085	HUFA76413DK8T-TF085
HUFA76419D3ST_SB82041A	HUFA76419D3ST-SB82041A
HUFA76429D3ST_F085	HUFA76429D3ST-F085
HUFA76633S3ST_S2575	HUFA76633S3ST-S2575
HUFA76645S3ST_F085	HUFA76645S3ST-F085
IRF634B_FP001	IRF634B-FP001
IRF644B_FP001	IRF644B-FP001
IRFM120ATF_T	IRFM120ATF-T
IRFM120A_NB82108	IRFM120A-NB82108
IRFNL210BTA_FP001	IRFNL210BTA-FP001
IRFU220BTU_AM002	IRFU220BTU-AM002
IRFW630BTM_FP001	IRFW630BTM-FP001
ISL9R1560G2_F085	ISL9R1560G2-F085
ISL9R1560P2_F085	ISL9R1560P2-F085
ISL9R1560P2_X	ISL9R1560P2-X
ISL9R18120W2_T	ISL9R18120W2-T
ISL9R2480G2_S2611	ISL9R2480G2-S2611
ISL9R3060G2_F085	ISL9R3060G2-F085
ISL9R460PF2_T	ISL9R460PF2-T
ISL9V2040S3ST_B9V002B	ISL9V2040S3ST-B9V002B
ISL9V2540S3ST_SB49015	ISL9V2540S3ST-SB49015
ISL9V3036D3ST_R4970	ISL9V3036D3ST-R4970
ISL9V3040D3ST_B49006A	ISL9V3040D3ST-B49006A
ISL9V3040D3ST_R4940	ISL9V3040D3ST-R4940
ISL9V3040D3ST_R4956	ISL9V3040D3ST-R4956
ISL9V3040D3ST_R4969	ISL9V3040D3ST-R4969
ISL9V3040D3ST_SB82150	ISL9V3040D3ST-SB82150
ISL9V3040D3ST_SB82253	ISL9V3040D3ST-SB82253
ISL9V3040P3_SB82030B	ISL9V3040P3-SB82030B
ISL9V3040S3ST_R4969	ISL9V3040S3ST-R4969
ISL9V3040S3ST_SB82252	ISL9V3040S3ST-SB82252



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
ISL9V5036P3_F085	ISL9V5036P3-F085
ISL9V5036S3ST_R4971	ISL9V5036S3ST-R4971
ISL9V5036S3ST_SN00208	ISL9V5036S3ST-SN00208
ISL9V5045S3ST_F085	ISL9V5045S3ST-F085
ISL9V5045S3ST_SN00222	ISL9V5045S3ST-SN00222
ISL9V5045S3ST_SN00339	ISL9V5045S3ST-SN00339
J109_D26Z	J109-D26Z
J111_D26Z	J111-D26Z
J111_D74Z	J111-D74Z
J112_D26Z	J112-D26Z
J112_D27Z	J112-D27Z
J112_D74Z	J112-D74Z
J113_D74Z	J113-D74Z
J175_D26Z	J175-D26Z
J176_D74Z	J176-D74Z
J211_D74Z	J211-D74Z
KA2904_T	KA2904-T
KA317TU_G	KA317TU-G
KA324_T	KA324-T
KA337TU_T	KA337TU-T
KA358A_T	KA358A-T
KA393_T	KA393-T
KA431AZTA_F065	KA431AZTA-F065
KA431AZTA_F081	KA431AZTA-F081
KA431SAMF2TF_T	KA431SAMF2TF-T
KA5L0380RYDTU_T	KA5L0380RYDTU-T
KA5M0280RYDTU_T	KA5M0280RYDTU-T
KA7553A_T	KA7553A-T
KA7812ETU_T	KA7812ETU-T
KA7815ETU_T	KA7815ETU-T
KA7818ETU_T	KA7818ETU-T
KA78L05AMTF_T	KA78L05AMTF-T
KA78M05RTM_T	KA78M05RTM-T
KA78R15CTU_T	KA78R15CTU-T
KA78RM33RTF_T	KA78RM33RTF-T
KA78RM33RTM_T	KA78RM33RTM-T
KA7905TU_T	KA7905TU-T
KA85_BAT54	KA85-BAT54
KDT00030ATR_SN00366	KDT00030ATR-SN00366
KSC2334YTU_T	KSC2334YTU-T



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
KSC2383YTA_T	KSC2383YTA-T
KSC5305DTU_F129	KSC5305DTU-F129
KSD1408YTU_T	KSD1408YTU-T
KSD1408YTU_X	KSD1408YTU-X
KSD526YTU_T	KSD526YTU-T
KSH122TF_T	KSH122TF-T
KSH122TF_X	KSH122TF-X
KSH42CTF_T	KSH42CTF-T
KSH42CTF_X	KSH42CTF-X
LM350T_T	LM350T-T
LM393AMX_T	LM393AMX-T
LM431SBCMFX_G	LM431SBCMFX-G
LM431SCCMFX_T	LM431SCCMFX-T
LM555CMX_T	LM555CMX-T
LM7815CT_T	LM7815CT-T
LM7818CT_T	LM7818CT-T
LMV321AS5X_G	LMV321AS5X-G
LY85_BZ84C8V2	LY85-BZ84C8V2
MB4S_F096	MB4S-F096
MJD122TF_T	MJD122TF-T
MJD2955TF_T	MJD2955TF-T
MJD31CETF_SN00207	MJD31CETF-SN00207
MJD41CTF_T	MJD41CTF-T
MJD44H11TM_T	MJD44H11TM-T
MJD50TF_T	MJD50TF-T
MJE340STU_T	MJE340STU-T
MM74HC00MTCX_T	MM74HC00MTCX-T
MM74HC04MX_SC162353	MM74HC04MX-SC162353
MM74HC04MX_XC162353	MM74HC04MX-XC162353
MM74HC14MX_SC162268	MM74HC14MX-SC162268
MM74HC14MX_SC162391	MM74HC14MX-SC162391
MM74HC14MX_XC162268	MM74HC14MX-XC162268
MM74HC14MX_XC162391	MM74HC14MX-XC162391
MM74HC32MX_SF501590	MM74HC32MX-SF501590
MM74HC32MX_XF501590	MM74HC32MX-XF501590
MM74HC74AMX_X	MM74HC74AMX-X
MMBD1205_F080	MMBD1205-F080
MMBD1503A_D87Z	MMBD1503A-D87Z
MMBD1505A_F165	MMBD1505A-F165
MMBD4148CA_F136	MMBD4148CA-F136



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
MMBD4148_D87Z	MMBD4148-D87Z
MMBF170_F169	MMBF170-F169
MMBF170_G	MMBF170-G
MMBFJ112_SB51338	MMBFJ112-SB51338
MMBT100_SB10217	MMBT100-SB10217
MMBT200_SB68107	MMBT200-SB68107
MMBT2222A_G	MMBT2222A-G
MMBT2369A_F080	MMBT2369A-F080
MMBT2907A_D87Z	MMBT2907A-D87Z
MMBT2907A_G	MMBT2907A-G
MMBT2907_D87Z	MMBT2907-D87Z
MMBT3904_G	MMBT3904-G
MMBT3906_G	MMBT3906-G
MMBT4401_G	MMBT4401-G
MMBT4403_D87Z	MMBT4403-D87Z
MMBT4403_F065	MMBT4403-F065
MMBT5087_NB68106	MMBT5087-NB68106
MMBT5088_NB10216	MMBT5088-NB10216
MMBT5401_D87Z	MMBT5401-D87Z
MMBT5401_SB74046	MMBT5401-SB74046
MMBT6428_SB10220	MMBT6428-SB10220
MMBTA14_NB05232	MMBTA14-NB05232
MMBTH81_F080	MMBTH81-F080
MMSD4148_D87Z	MMSD4148-D87Z
MPS751_D26Z	MPS751-D26Z
MPSA29_D26Z	MPSA29-D26Z
NC7S00P5X_F40	NC7S00P5X-F40
NC7S08M5X_SF500951	NC7S08M5X-SF500951
NC7S08P5X_F080	NC7S08P5X-F080
NC7S08P5X_F40	NC7S08P5X-F40
NC7S14M5X_SF500948	NC7S14M5X-SF500948
NC7S14P5X_F40	NC7S14P5X-F40
NC7S32M5X_F080	NC7S32M5X-F080
NC7S32P5X_G	NC7S32P5X-G
NC7SB3157L6X_F131	NC7SB3157L6X-F131
NC7SB3157P6X_F080	NC7SB3157P6X-F080
NC7SB3157P6X_F40	NC7SB3157P6X-F40
NC7SP08L6X_T	NC7SP08L6X-T
NC7SPU04L6X_T	NC7SPU04L6X-T
NC7ST08P5X_F40	NC7ST08P5X-F40



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
NC7SZ00P5X_F40	NC7SZ00P5X-F40
NC7SZ04P5X_F40	NC7SZ04P5X-F40
NC7SZ05FHX_T	NC7SZ05FHX-T
NC7SZ05P5X_F40	NC7SZ05P5X-F40
NC7SZ08M5X_SN00135	NC7SZ08M5X-SN00135
NC7SZ08P5X_F40	NC7SZ08P5X-F40
NC7SZ125P5X_F40	NC7SZ125P5X-F40
NC7SZ126L6X_F106	NC7SZ126L6X-F106
NC7SZ126P5X_F080	NC7SZ126P5X-F080
NC7SZ14P5X_F080	NC7SZ14P5X-F080
NC7SZ14P5X_F40	NC7SZ14P5X-F40
NC7SZ157P6X_F40	NC7SZ157P6X-F40
NC7SZ175P6X_F080	NC7SZ175P6X-F080
NC7SZ32P5X_F40	NC7SZ32P5X-F40
NC7SZ66L6X_T	NC7SZ66L6X-T
NC7SZ86FHX_T	NC7SZ86FHX-T
NC7SZ86M5X_SF500979	NC7SZ86M5X-SF500979
NC7SZU04P5X_F40	NC7SZU04P5X-F40
NC7WZ04P6X_F080	NC7WZ04P6X-F080
NC7WZ14P6X_F40	NC7WZ14P6X-F40
NC7WZ16P6X_F40	NC7WZ16P6X-F40
NC7WZ17L6X_F106	NC7WZ17L6X-F106
NDB6030PL_F169	NDB6030PL-F169
NDB6060L_T	NDB6060L-T
NDB6060L_X	NDB6060L-X
NDC7001C_X	NDC7001C-X
NDC7001C_Z	NDC7001C-Z
NDC7002N_F169	NDC7002N-F169
NDC7003P_F169	NDC7003P-F169
NDP6020P_F169	NDP6020P-F169
NDS0605_F169	NDS0605-F169
NDS0610_F169	NDS0610-F169
NDS0610_F169G	NDS0610-F169G
NDS0610_G	NDS0610-G
NDS0610_PG	NDS0610-PG
NDS0610_T	NDS0610-T
NDS0610_TG	NDS0610-TG
NDS331N_F169	NDS331N-F169
NDS331N_T	NDS331N-T
NDS332P_F169	NDS332P-F169



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
NDS332P_T	NDS332P-T
NDS351AN_SBNL001	NDS351AN-SBNL001
NDS351AN_SBNL001P	NDS351AN-SBNL001P
NDS351AN_TSBNL001	NDS351AN-TSBNL001
NDS351N_F169	NDS351N-F169
NDS352AP_F169	NDS352AP-F169
NDS352AP_T	NDS352AP-T
NDS355AN_F169	NDS355AN-F169
NDS355AN_F169G	NDS355AN-F169G
NDS355AN_NB9L007A	NDS355AN-NB9L007A
NDS356AP_F169	NDS356AP-F169
NDS356AP_NB8L005A	NDS356AP-NB8L005A
NDS356AP_TB8L005A	NDS356AP-TB8L005A
NDS7002A_F169	NDS7002A-F169
NDS8425_F169	NDS8425-F169
NDS8434_F169	NDS8434-F169
NDS9407_F169	NDS9407-F169
NDS9407_T	NDS9407-T
NDS9948_F169	NDS9948-F169
NDS9952A_F011	NDS9952A-F011
NDS9952A_F169	NDS9952A-F169
NDT014L_F169	NDT014L-F169
NDT014L_SB9D008	NDT014L-SB9D008
NDT014L_SB9D008P	NDT014L-SB9D008P
NDT2955_F169	NDT2955-F169
NDT2955_X	NDT2955-X
NDT3055L_F169	NDT3055L-F169
NDT451AN_F169	NDT451AN-F169
NDT454P_F169	NDT454P-F169
NDT456P_F169	NDT456P-F169
OI1010B_W	OI1010B-W
OI1015_M	OI1015-M
OI1017_M	OI1017-M
OI1505_021M	OI1505-021M
OI1527031A_W	OI1527031A-W
OI1527_12M	OI1527-12M
OI1530_23M	OI1530-23M
OI4001271_W	OI4001271-W
PC47_BPC001B	PC47-BPC001B
PCF045AN08W_R4800	PCF045AN08W-R4800



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
PCF2532W_R4800	PCF2532W-R4800
PCF430NZW_SN00383	PCF430NZW-SN00383
PCF75307W_R4903	PCF75307W-R4903
PCF75337D_SN00209	PCF75337D-SN00209
PCF75337W_S2496	PCF75337W-S2496
PCFC47N60FW_SN00201	PCFC47N60FW-SN00201
PCG20N60A4W_R4800	PCG20N60A4W-R4800
PCRU420D_R4707	PCRU420D-R4707
PCRU420D_R4707P	PCRU420D-R4707P
PN100TF_G	PN100TF-G
Q0504_M	Q0504-M
QED223A4R0_0238	QED223A4R0-0238
QED223_0227	QED223-0227
QED223_0238	QED223-0238
QED234_0201	QED234-0201
QRE1113GR_SN00394	QRE1113GR-SN00394
QRE1113_0216	QRE1113-0216
QSB34CGR_F170	QSB34CGR-F170
QSB34GR_SN00349	QSB34GR-SN00349
QSD124_0226	QSD124-0226
QSE113_0203	QSE113-0203
QSE114_0219	QSE114-0219
QSE773_0231	QSE773-0231
RA9100_32	RA9100-32
RHRD660S9A_F085	RHRD660S9A-F085
RHRD660S9A_S2515	RHRD660S9A-S2515
RHRD660S9A_S2515P	RHRD660S9A-S2515P
RHRD660S9A_SB82141	RHRD660S9A-SB82141
RHRD660S9A_SB82141P	RHRD660S9A-SB82141P
RHRD660S9A_SB82182	RHRD660S9A-SB82182
RHRD660S9A_SN00162	RHRD660S9A-SN00162
RHRD660S9A_T	RHRD660S9A-T
RHRD660S9A_W49010A	RHRD660S9A-W49010A
RHRG1560CC_F085	RHRG1560CC-F085
RHRG1560_F085	RHRG1560-F085
RHRG3060_DCR3500	RHRG3060-DCR3500
RHRG3060_F085	RHRG3060-F085
RHRG5060_F085	RHRG5060-F085
RHRP15120_F102	RHRP15120-F102
RHRP1560_F102	RHRP1560-F102



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
RHRP30120_F102	RHRP30120-F102
RHRP3060_F102	RHRP3060-F102
RHRP8120_F102	RHRP8120-F102
RHRP860_F085	RHRP860-F085
RHRP860_F102	RHRP860-F102
RHRP860_R4647	RHRP860-R4647
RHRP860_R4647P	RHRP860-R4647P
RHRP860_TR4647	RHRP860-TR4647
RS1K_F080	RS1K-F080
RURD4120S9A_F085	RURD4120S9A-F085
RURD4120S9A_SB82080	RURD4120S9A-SB82080
RURD4120S9A_SB82080P	RURD4120S9A-SB82080P
RURD4120S9A_TSB82080	RURD4120S9A-TSB82080
RURD620CCS9A_F085	RURD620CCS9A-F085
RURD620CCS9A_F085P	RURD620CCS9A-F085P
RURD620CCS9A_SB82068	RURD620CCS9A-SB82068
RURD620CCS9A_SB82068P	RURD620CCS9A-SB82068P
RURD620CCS9A_SB82215	RURD620CCS9A-SB82215
RURD620CCS9A_SB82215P	RURD620CCS9A-SB82215P
RURD620CCS9A_TF085	RURD620CCS9A-TF085
RURD620CCS9A_TSB82068	RURD620CCS9A-TSB82068
RURD620S9A_S2457	RURD620S9A-S2457
RURD620S9A_S2457P	RURD620S9A-S2457P
RURD660S9A_F085	RURD660S9A-F085
RURD660S9A_F085P	RURD660S9A-F085P
RURD660S9A_SB82111	RURD660S9A-SB82111
RURD660S9A_SB82111P	RURD660S9A-SB82111P
RURD660S9A_TF085	RURD660S9A-TF085
RURD660S9A_TSB82111	RURD660S9A-TSB82111
RURD660S_SB82214	RURD660S-SB82214
RURD660S_TSB82214	RURD660S-TSB82214
RURG3060CC_F085	RURG3060CC-F085
RURG3060_F085	RURG3060-F085
RURG5060_F085	RURG5060-F085
RURG5060_R4857	RURG5060-R4857
RURG80100_F085	RURG80100-F085
RURG8060_F085	RURG8060-F085
RURP15100_F085	RURP15100-F085
RURP15100_F085P	RURP15100-F085P
RURP15100_TF085	RURP15100-TF085



List of Affected Part(s):

Current Legacy Fairchild Part Number	New Part Number (starting October 30 th , 2017)
RURP1560_F085	RURP1560-F085
RURP1560_F085P	RURP1560-F085P
RURP1560_TF085	RURP1560-TF085
RY85_MBZ5240B	RY85-MBZ5240B
S310_G	S310-G
S3M_F065	S3M-F065
SFW9640TM_SBEA021	SFW9640TM-SBEA021
SFW9640TM_TSBEA021	SFW9640TM-TSBEA021
SI3443DV_F169	SI3443DV-F169
SI4467DY_BAA005AP	SI4467DY-BAA005AP
SI4467DY_SBAA005A	SI4467DY-SBAA005A
SI4532DY_F169	SI4532DY-F169
SI4542DY_F169	SI4542DY-F169
SI4542DY_T	SI4542DY-T
SI4542DY_Z	SI4542DY-Z
SMC6100P_T	SMC6100P-T
SSR1N60BTM_WS	SSR1N60BTM-WS
SSU1N60BTU_WS	SSU1N60BTU-WS
TIP117TU_T	TIP117TU-T
TIP120TU_F129	TIP120TU-F129
TIP122TU_F129	TIP122TU-F129
TIP31CTU_F129	TIP31CTU-F129
TIP32CTU_F129	TIP32CTU-F129
TIP41CTU_F129	TIP41CTU-F129
TIP42CTU_F129	TIP42CTU-F129
TIP42CTU_T	TIP42CTU-T
TS85_BZX84C12	TS85-BZX84C12
WY85_BZX84C15	WY85-BZX84C15
ZY85_BZX84C18	ZY85-BZX84C18



Appendix A: Changed Products

PCN Number : P751AAB

Customer Name

Product	Customer Part Number	BBB	Drawing
1N4148_T26A		Y	N
1N4148_T50R		Y	N
1N4746A_T50A		Y	N
1N4747A_T50A		Y	N
1N4755A_T50A		Y	N
1N914_T50A	1N914_T50A	Y	N
2N7000_D26Z		Y	N
2N7000_D74Z		Y	N
2N7000_D75Z		Y	N
BAS31_D87Z		Y	N
BAT54S_D87Z		Y	N
BAT54_D87Z		Y	N
BAV99_D87Z		Y	N
BC516_D27Z		Y	N
BC517_D74Z		Y	N
BC63916_D27Z		Y	N
BC63916_D74Z		Y	N
BS170_D26Z		Y	N
BS170_D27Z		Y	N
BS170_D74Z		Y	N
BS170_D75Z		Y	N
BUZ11_NR4941		Y	N
BZX79C15_T50R		Y	N
BZX79C16_T50A		Y	N
BZX79C18_T50A		Y	N
BZX79C6V2_T50R		Y	N
BZX85C10_T50R		Y	N
BZX85C18_T50R		Y	N
BZX85C24_T50R		Y	N
FAN3228CMX_F085		Y	N
FAN3988IL6X_F113		Y	N
FAN4010IL6X_F113		Y	N
FAN7085MX_GF085		Y	N
FAN7171MX_F085		Y	N
FAN7190MX_F085		Y	N
FCH040N65S3_F155		Y	N
FCH47N60F_F133		Y	N
FDB12N50FTM_WS		Y	N
FDB3632_F085		Y	N
FDB9403_F085		Y	N



FDC5661N_F085		Y	N
FDD24AN06LA0_F085		Y	N
FDD4141_F085		Y	N
FDD6N50TM_WS		Y	N
FDD8445_F085		Y	N
FDD8447L_F085		Y	N
FDD86567_F085		Y	N
FDD9409_F085		Y	N
FDG6301N_F085		Y	N
FDG6332C_F085		Y	N
FDLL4148_D87Z		Y	N
FDMS5360L_F085		Y	N
FDMS5362L_F085		Y	N
FDP020N06B_F102		Y	N
FDP085N10A_F102		Y	N
FDS4141_F085		Y	N
FDS4435BZ_F085		Y	N
FDS4675_F085		Y	N
FDS6898AZ_F085		Y	N
FDS8958A_F085		Y	N
FDS9958_F085		Y	N
FFD08S60S_F085		Y	N
FGA25N120ANTDTU_F109		Y	N
FGB40T65SPD_F085		Y	N
FGD3040G2_F085		Y	N
FGD3440G2_F085		Y	N
FGH30T65UPDT_F155		Y	N
FGH40T120SMD_F155		Y	N
FGH60T65SHD_F155		Y	N
FODM3052R2_NF098		Y	N
FODM3052_NF098		Y	N
FODM3053R2V_NF098		Y	N
FODM3053R2_NF098		Y	N
FQA13N80_F109		Y	N
FQA9N90C_F109		Y	N
FQB22P10TM_F085		Y	N
FQB47P06TM_AM002		Y	N
FQB7P20TM_F085		Y	N
FQD12P10TM_F085		Y	N
FQD3N60CTM_WS		Y	N
FQD4P25TM_WS		Y	N
FQT1N60CTF_WS		Y	N
FSUSB43L10X_F131		Y	N
J109_D26Z		Y	N
J111_D26Z		Y	N
J112_D26Z		Y	N
J113_D74Z		Y	N
J175_D26Z		Y	N
J176_D74Z		Y	N
J211_D74Z		Y	N



MMBD4148_D87Z		Y	N
MMBT2907A_D87Z		Y	N
MPS751_D26Z		Y	N
MPSA29_D26Z		Y	N
RHRD660S9A_F085		Y	N

Appendix A: Changed Products

PCN Number : P751AAB

Customer Name :

Product	Customer Part Number	BBB	Drawing
1N4148_T50A		Y	N
1N459_T50R		Y	N
1N4728A_T50A		Y	N
1N4730A_T50A		Y	N
1N4731A_T50A		Y	N
1N4732A_T50A		Y	N
1N4733A_T50A		Y	N
1N4733A_T50R		Y	N
1N4734A_T50R		Y	N
1N4735A_T50R		Y	N
1N4736A_T50A		Y	N
1N4736A_T50R		Y	N
1N4737A_T50A		Y	N
1N4738A_T50A		Y	N
1N4738A_T50R		Y	N
1N4739A_T50A		Y	N
1N4740A_T50A		Y	N
1N4741A_T50A		Y	N
1N4743A_T50A		Y	N
1N4744A_T50R		Y	N
1N4746A_T50A		Y	N
1N4747A_T50A		Y	N
1N4748A_T50A		Y	N
1N4749A_T50A		Y	N
1N4749A_T50R		Y	N
1N4750A_T50A		Y	N
1N4751A_T50A		Y	N
1N4752A_T50A		Y	N
1N4753A_T50A		Y	N
1N4754A_T50A		Y	N
1N4755A_T50A		Y	N
1N4758A_T50A		Y	N
1N486B_T50A		Y	N
1N5260B_T50A		Y	N
1N5262B_T50A		Y	N
1N5263B_T50R		Y	N
1N914_T50A		Y	N
BAS16_D87Z		Y	N
BAS31_D87Z		Y	N
BAV21_T50A		Y	N



BAV21_T50R		Y	N
BAV99_D87Z		Y	N
BAW74_D87Z		Y	N
BC517_D74Z		Y	N
BC63916_D74Z		Y	N
BS170_D74Z		Y	N
BS270_D74Z		Y	N
BZX79C10_T50A		Y	N
BZX79C11_T50A		Y	N
BZX79C12_T50A		Y	N
BZX79C13_T50A		Y	N
BZX79C15_T50A		Y	N
BZX79C15_T50R		Y	N
BZX79C16_T50A		Y	N
BZX79C20_T50A		Y	N
BZX79C24_T50A		Y	N
BZX79C27_T50A		Y	N
BZX79C2V4_T50A		Y	N
BZX79C2V7_T50A		Y	N
BZX79C30_T50A		Y	N
BZX79C33_T50A		Y	N
BZX79C36_T50A		Y	N
BZX79C3V3_T50A		Y	N
BZX79C3V6_T50A		Y	N
BZX79C3V9_T50A		Y	N
BZX79C4V3_T50A		Y	N
BZX79C4V7_T50A		Y	N
BZX79C51_T50A		Y	N
BZX79C5V1_T50A		Y	N
BZX79C5V6_T50A		Y	N
BZX79C6V2_T50A		Y	N
BZX79C6V2_T50R		Y	N
BZX79C6V8_T50A		Y	N
BZX79C7V5_T50A		Y	N
BZX79C8V2_T50A		Y	N
BZX79C9V1_T50A		Y	N
BZX85C10_T50R		Y	N
BZX85C12_T50R		Y	N
BZX85C15_T50A		Y	N
BZX85C15_T50R		Y	N
BZX85C18_T50A		Y	N
BZX85C18_T50R		Y	N
BZX85C24_T50R		Y	N
BZX85C5V1_T50A		Y	N
BZX85C5V6_T50R		Y	N
BZX85C6V2_T50A		Y	N
FAN1100_F085		Y	N
FAN156L6X_F106		Y	N
FAN302HLMY_F117		Y	N
FAN3121CMX_F085		Y	N



FAN3121TMX_F085		Y	N
FAN3122CMX_F085		Y	N
FAN3122TMX_F085		Y	N
FAN3213TMX_F085		Y	N
FAN3214TMX_F085		Y	N
FAN3216TMX_F085		Y	N
FAN3217TMX_F085		Y	N
FAN3223CMX_F085		Y	N
FAN3223TMX_F085		Y	N
FAN3224TMX_F085		Y	N
FAN3225CMX_F085		Y	N
FAN3225TMX_F085		Y	N
FAN3226CMX_F085		Y	N
FAN3226TMX_F085		Y	N
FAN3227CMX_F085		Y	N
FAN3227TMX_F085		Y	N
FAN3228CMX_F085		Y	N
FAN3228TMX_F085		Y	N
FAN3229CMX_F085		Y	N
FAN3229TMX_F085		Y	N
FAN3268TMX_F085		Y	N
FAN7080MX_GF085		Y	N
FAN7080M_GF085		Y	N
FAN7081M_GF085		Y	N
FAN7083MX_GF085		Y	N
FAN7083M_GF085		Y	N
FAN7085M_GF085		Y	N
FAN7093_F085		Y	N
FAN7171M_F085		Y	N
FAN7190M_F085		Y	N
FAN7930BMX_G		Y	N
FAN7930CMX_G		Y	N
FCB20N60F_F085		Y	N
FCB20N60_F085		Y	N
FCD5N60TM_WS		Y	N
FCD5N60_F085		Y	N
FCD7N60TM_WS		Y	N
FCH023N65S3_F155		Y	N
FCH041N60F_F085		Y	N
FCH041N65EF_F155		Y	N
FCH041N65F_F085		Y	N
FCH041N65F_F155		Y	N
FCH060N80_F155		Y	N
FCH067N65S3_F155		Y	N
FCH072N60F_F085		Y	N
FCH077N65F_F085		Y	N
FCH077N65F_F155		Y	N
FCH104N60F_F085		Y	N
FCH110N65F_F155		Y	N
FCH150N65F_F155		Y	N



FCH190N65F_F085		Y	N
FCH190N65F_F155		Y	N
FCH47N60F_F085		Y	N
FCI25N60N_F102		Y	N
FCP190N60_GF102		Y	N
FCP25N60N_F102		Y	N
FCPF260N60E_F152		Y	N
FDA16N50_F109		Y	N
FDB035AN06A0_F085		Y	N
FDB070AN06A0_F085		Y	N
FDB12N50FTM_WS		Y	N
FDB2532_F085		Y	N
FDB2552_F085		Y	N
FDB3632_F085		Y	N
FDB3652_F085		Y	N
FDB3672_F085		Y	N
FDB42AN15A0_F085		Y	N
FDB8160_F085		Y	N
FDB8441_F085		Y	N
FDB8442_F085		Y	N
FDB8443_F085		Y	N
FDB8445_F085		Y	N
FDB86360_F085		Y	N
FDB86363_F085		Y	N
FDB86366_F085		Y	N
FDB86563_F085		Y	N
FDB86566_F085		Y	N
FDB8832_F085		Y	N
FDB8860_F085		Y	N
FDB9403L_F085		Y	N
FDB9406_F085		Y	N
FDBL86210_F085		Y	N
FDBL86361_F085		Y	N
FDBL86363_F085		Y	N
FDBL86366_F085		Y	N
FDBL86561_F085		Y	N
FDBL86563_F085		Y	N
FDBL86566_F085		Y	N
FDBL9401_F085		Y	N
FDBL9403_F085		Y	N
FDBL9406_F085		Y	N
FDBS09H04A_F085A		Y	N
FDC642P_F085		Y	N
FDD10AN06A0_F085		Y	N
FDD120AN15A0_F085		Y	N
FDD13AN06A0_F085		Y	N
FDD14AN06LA0_F085		Y	N
FDD16AN08A0_F085		Y	N
FDD20AN06A0_F085		Y	N
FDD2572_F085		Y	N



FDD26AN06A0_F085		Y	N
FDD3672_F085		Y	N
FDD3682_F085		Y	N
FDD4243_F085		Y	N
FDD4685_F085		Y	N
FDD5N50FTM_WS		Y	N
FDD5N50UTM_WS		Y	N
FDD6637_F085		Y	N
FDD6N50TM_F085		Y	N
FDD8424H_F085A		Y	N
FDD8444L_F085		Y	N
FDD8453LZ_F085		Y	N
FDD86367_F085		Y	N
FDD86369_F085		Y	N
FDD86380_F085		Y	N
FDD86381_F085		Y	N
FDD86567_F085		Y	N
FDD86569_F085		Y	N
FDD86580_F085		Y	N
FDD8870_F085		Y	N
FDD8896_F085		Y	N
FDD9407L_F085		Y	N
FDD9407_F085		Y	N
FDD9409_F085		Y	N
FDD9410_F085		Y	N
FDD9411_F085		Y	N
FDDS100H06_F085		Y	N
FDG6301N_F085		Y	N
FDI045N10A_F102		Y	N
FDI9406_F085		Y	N
FDI9409_F085		Y	N
FDLL4448_D87Z		Y	N
FDMA1028NZ_F021		Y	N
FDMC4435BZ_F126		Y	N
FDMC7672S_F126		Y	N
FDMC7692S_F126		Y	N
FDMC8884_F126		Y	N
FDMS36101L_F085		Y	N
FDMS5360L_F085		Y	N
FDMS5361L_F085		Y	N
FDMS86368_F085		Y	N
FDMS86369_F085		Y	N
FDMS86380_F085		Y	N
FDMS86381_F085		Y	N
FDMS86568_F085		Y	N
FDMS86569_F085		Y	N
FDMS86580_F085		Y	N
FDMS9408L_F085		Y	N
FDMS9408_F085		Y	N
FDMS9409_F085		Y	N



FDMS9410L_F085		Y	N
FDMS9410_F085		Y	N
FDMS9411L_F085		Y	N
FDMS9411_F085		Y	N
FDN5632N_F085		Y	N
FDP023N08B_F102		Y	N
FDP027N08B_F102		Y	N
FDP030N06B_F102		Y	N
FDP032N08B_F102		Y	N
FDP039N08B_F102		Y	N
FDP045N10A_F102		Y	N
FDP053N08B_F102		Y	N
FDP075N15A_F102		Y	N
FDP085N10A_F102		Y	N
FDP150N10A_F102		Y	N
FDP2710_F085		Y	N
FDP5500_F085		Y	N
FDP8442_F085		Y	N
FDP8443_F085		Y	N
FDP86363_F085		Y	N
FDP8870_F085		Y	N
FDPF18N20FT_G		Y	N
FDPF7N50U_G		Y	N
FDS2672_F085		Y	N
FDS4465_F085		Y	N
FDS4559_F085		Y	N
FDS6673BZ_F085		Y	N
FDS8449_F085		Y	N
FDS8949_F085		Y	N
FDS9958_F085		Y	N
FDV302P_NB8V001		Y	N
FDWS86368_F085		Y	N
FDWS86369_F085		Y	N
FFB20UP20DN_F085		Y	N
FFH50US60S_F085		Y	N
FFPF20UP60DNTU_G		Y	N
FFSH20120ADN_F155		Y	N
FFSH40120ADN_F155		Y	N
FGA15N120ANTDTU_F109		Y	N
FGA20S125P_SN00336		Y	N
FGA25S125P_SN00337		Y	N
FGB20N60SFD_F085		Y	N
FGB3040G2_F085		Y	N
FGB3236_F085		Y	N
FGB3245G2_F085		Y	N
FGB3440G2_F085		Y	N
FGD3040G2_F085		Y	N
FGD3245G2_F085		Y	N
FGH15T120SMD_F155		Y	N
FGH20N60SFDTU_F085		Y	N



FGH25T120SMD_F155		Y	N
FGH40N60SFDTU_F085		Y	N
FGH40N60SMD_F085		Y	N
FGH40T100SMD_F155		Y	N
FGH40T65SHDF_F155		Y	N
FGH40T65SHD_F155		Y	N
FGH40T65SH_F155		Y	N
FGH40T65SPD_F155		Y	N
FGH60N60SFDTU_F085		Y	N
FGH60N60SMD_F085		Y	N
FGH60T65SHD_F155		Y	N
FGH75T65SHD_F155		Y	N
FGH75T65SQD_F155		Y	N
FGH75T65UPD_F085		Y	N
FGI3040G2_F085		Y	N
FGI3236_F085		Y	N
FGP3040G2_F085		Y	N
FGP3440G2_F085		Y	N
FGY120T65SPD_F085		Y	N
FGY160T65SPD_F085		Y	N
FL7930BMX_G		Y	N
FL7930CMX_G		Y	N
FODM3012R2_NF098		Y	N
FODM3012_NF098		Y	N
FODM3022R2_NF098		Y	N
FODM3022_NF098		Y	N
FODM3023R2_NF098		Y	N
FODM3023R4_NF098		Y	N
FODM3023_NF098		Y	N
FODM3052R2_NF098		Y	N
FODM3053_NF098		Y	N
FPF2280BUCX_F130		Y	N
FPF2281BUCX_F130		Y	N
FPF2290BUCX_F130		Y	N
FPF2411BUCX_F130		Y	N
FQA11N90_F109		Y	N
FQA13N50C_F109		Y	N
FQA16N50_F109		Y	N
FQA7N80C_F109		Y	N
FQA8N90C_F109		Y	N
FQA90N15_F109		Y	N
FQA9N90_F109		Y	N
FQB10N50CFTM_WS		Y	N
FQB27N25TM_F085		Y	N
FQB5N60CTM_WS		Y	N
FQB7N60TM_WS		Y	N
FQB8N60CTM_WS		Y	N
FQD2N60CTM_WS		Y	N
FQD3N60CTM_WS		Y	N
FQD4P40TM_AM002		Y	N



FQD5N60CTM_WS		Y	N
FQD8P10TM_F085		Y	N
FQD9N25TM_F080		Y	N
FQD9N25TM_F085		Y	N
FQH44N10_F133		Y	N
FQI27N25TU_F085		Y	N
FQP2P40_F080		Y	N
FQU13N06LTU_WS		Y	N
FQU2N50BTU_WS		Y	N
FQU2N90TU_AM002		Y	N
FSA2567UMX_F135		Y	N
FXLA0104QFX_F106		Y	N
FXMAR2102UMX_F106		Y	N
HUF76419S3ST_F085		Y	N
HUF76629D3ST_F085		Y	N
HUF76633P3_F085		Y	N
HUF76633S3ST_F085		Y	N
HUF76639S3ST_F085		Y	N
HUFA75639S3ST_F085A		Y	N
HUFA75852G3_F085		Y	N
HUFA76429D3ST_F085		Y	N
HUFA76645S3ST_F085		Y	N
IRFU220BTU_AM002		Y	N
ISL9R1560G2_F085		Y	N
ISL9R1560P2_F085		Y	N
ISL9R3060G2_F085		Y	N
ISL9V5045S3ST_F085		Y	N
J109_D26Z		Y	N
J111_D74Z		Y	N
J112_D27Z		Y	N
J112_D74Z		Y	N
J211_D74Z		Y	N
MMBD1503A_D87Z		Y	N
MMBT2907_D87Z		Y	N
MMBT4403_D87Z		Y	N
MMBT5401_D87Z		Y	N
MPS751_D26Z		Y	N
MPSA29_D26Z		Y	N
NC7SB3157P6X_F080		Y	N
NC7SB3157P6X_F40		Y	N
RHRG1560CC_F085		Y	N
RHRG1560_F085		Y	N
RHRG3060_F085		Y	N
RHRG5060_F085		Y	N
RURD4120S9A_F085		Y	N
RURD620CCS9A_F085		Y	N
RURD660S9A_F085		Y	N
RURG3060CC_F085		Y	N
RURG3060_F085		Y	N
RURG5060_F085		Y	N



RURG80100_F085		Y	N
RURG8060_F085		Y	N
RURP15100_F085		Y	N
RURP1560_F085		Y	N

Appendix A: Changed Products

PCN Number : P751AAB

Customer Name :

Product	Customer Part Number	BBB	Drawing
FAN1100_F085		Y	N
FAN7930BMX_G		Y	N
FCH110N65F_F155		Y	N
FDB3632_F085		Y	N
FDB86360_F085		Y	N
FDBL86210_F085		Y	N
FGH60T65SHD_F155		Y	N
FGY160T65SPD_F085		Y	N
FQA11N90_F109		Y	N
ISL9R3060G2_F085		Y	N
RURP15100_F085		Y	N



Appendix A: Changed Products

PCN Number : P751AAB

Customer Name :

Product	Customer Part Number	BBB	Drawing
FGD3325G2_F085		Y	N