

PCN Number:	20180517001	PCN Date:	June 5, 2018
Title:	Datasheet for TPS7B6701-Q1, TPS7B6733-Q1, TPS7B6750-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process

Notification Details

Description of Change:

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



TEXAS
INSTRUMENTS

TPS7B6701-Q1
TPS7B6733-Q1, TPS7B6750-Q1
SLVSCB2D – OCTOBER 2013 – REVISED APRIL 2018

Changes from Revision C (December 2014) to Revision D

Page

- Added Dropout Recovery section explaining LDO behavior when exiting dropout 17

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS7B6701-Q1, TPS7B6733-Q1, TPS7B6750-Q1	SLVSCB2C	SLVSCB2D

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/TPS7B67-Q1>

Reason for Change:

To accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

Changes to product identification resulting from this PCN:

None.

Product Affected:

TPS7B6701QPWPRQ1	TPS7B6733QPWPRQ1	TPS7B6750QPWPRQ1	
------------------	------------------	------------------	--

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com